

## MicroConverter®, Dual-Channel 16 bit ADCs with Embedded FLASH MCU

Errata Sheet ADuC816

A. This Errata sheet represents the known bugs, anomalies and work-arounds for the ADuC816 MicroConverter.

B. The Errata listed, apply to all ADuC816 packaged material branded as follows :

(Sampling Material)

ADUC816BS

Date Stamp AD Logo
Lot Number

- C. Analog Devices Inc. is committed, through future silicon revisions to continuously improve silicon functionality. Analog Devices Inc. will use its best endeavors to ensure that these future silicon revisions remain compatible with your present software/systems implementing the recommended work-arounds outlined in this document.
- D. ADuC816 Silicon Errata Sheet Revision History:

Revision	Date :	Relevance	Silicon Status	# of Bugs Reported
A.0	Feb. `01	All Silicon branded ADUC816BS	Released	1 - 816_01

ADuC816 Silicon - Errata Sheet

## # 816\_01. INDIRECT ADDRESSING MODE-:

Background: In indirect addressing the instruction specifies a register which contains the address of

the operand. Both internal and external RAM can be indirectly addressed.

eg. MOV A, @R0.

Issue: The following Special Function Registers (SFRs) cannot be read using indirect

addressing modes: ADCMODE, ADC0CON, ADC1CON, SF, ICON, PSMCON,

ADCSTAT, ADC0L/M/H, ADC1L/H, OF0L/M/H, OF1L/H, GN0L/M/H,

GN1L/H, DACL/H, DACCON.

Work-Around: Instead of executing the indirectly addressed read instruction as

MOV @Ri, ADCSTAT

It should instead be executed as

MOV A, ADCSTAT

MOV @Ri, A

Related Issues: Reading, using indirect addressing, functions correctly for all SFRs other than those

mentioned above.

Writing, using indirect addressing, functions correctly for all SFRs including those

mentioned above.