
Product:	Texas Instruments OPAx863 Low-Power High-Speed Operational Amplifiers	TEXAS INSTRUMENTS	MOUSER
Description:	Unity-gain stable, rail-to-rail input/output, voltage-feedback operational amplifiers that operates over a power supply range of 2.7–12.6V.	Download Datasheet	



Newbie Posts: 3



Thanks for your reply. The GPS-3030 is similar but different from the 305. Different PCB's and layout. But I'll keep hoping that someone will come up with a schematic for the GPS-3030. I believe the instek 3030 and the Tenma 72-6610 are similar. Thanks - Bob VK2ZRM

> Logged Report to moderator



Newbie

Posts: 3





Sav Thanks Reply Quote

Well, the GPS-3030 is repaired and working well, so I thought I'd write a few words about the repair. In its day, this must have been quite a nice, professional bench power supply. It's very nicely made. The original symptom was that it appeared to be working till any sort of load was put on the output. Then it would die. I searched the internet and blogs (including EEVBlog) for a schematic. No joy. I downloaded the manual which has a block diagram, but no schematic. I removed the main PCB and gave it a thorough eyeball for obvious issues. The +15V and -15V references had been replaced previously and curiously, a 4.7K 3W resistor that goes across the input smoothing capacitor had been removed and placed in a plastic bag, inside the cabinet. I then checked every resistor, diode, zener and transistor with a multimeter. Also checked and cleaned connectors. No joy!, Next I powered the supply up and checked that input voltages, the +/- 15V and 2.5V references were working. Everything checked out, but still not working and without a schematic that was about as far as I could get. So, what did I have to lose? I removed the 4 IC's and fitted high quality IC sockets, then replaced the IC's with new devices. Joy oh joy!! The GPS-3030 was now working like a beauty! The four IC's are U103A/B Im1458 Voltage/Current reference amplifier. U104 LM301 Voltage Comparitor. U105 LM301 Current Comparitor and U106 LM741 Current Amplifier. I haven't tested which one is faulty, but who cares now that the supply is working? The manual has the adjustment procedure which I carried out, so it's working like a bought one. Bob VK2ZRM

Report to moderator Logged

Reply

Say Thanks

Sav Thanks



Quote

Quote

□ sbrisebois

Newbie

Posts: 1 Country: 🔄





« Reply #4 on: June 29, 2019, 03:21:07 am »

Hi!

I just found the issue with my GPS-3030, the +/- 15VDC cap before the regulator was causing problem. They are not short either open, but when the voltage raise up to 5v on them, they began to draw a lot of current. This cause the two 315ma fuses to blown and the supply to not work at all. I just replace the two 470uf 35vdc capacitor by brand new ones (and the two fuse of course 👝), and I have now a fully operational supply.

> Report to moderator Logaed

> > Reply



Regular Contributor





Country: 💂 🖂 💭




explanation).

I'm hoping that someone can point me in the direction of a schematic.

Re: Good Will GPS-3030 Schematic -

Repaired and Working (see my

« Reply #5 on: July 08, 2019, 12:28:05 am »



GPS-3030.png (173.59 kB, 1261x897 - viewed 3866 times.)

« Last Edit: July 08, 2019, 12:35:12 am by RomDump »

Report to moderator Logged

RomDump

The following users thanked this post: coromonadalix

SEND THIS TOPIC SEARCH « previous next »

Share me

Pages: [1] Go Up















NOTIFY



MARK UNREAD

EEVblog Electronics Community Forum » Electronics » Repair » Good Will GPS-3030 Schematic - Repaired and Working (see my explanation).

LINK TO CALENDAR

Jump to: | => Repair ❤ | go

Quick Reply

ELECTRONIC DESIGN AND TEST DAYS 2021









EEVblog Main Site

EEVblog on Youtube

EEVblog on Twitter

EEVblog on Facebook

EEVblog on Library

SMF 2.0.18 | SMF © 2021, Simple Machines Simple Audio Video Embedder SMFAds for Free Forums XHTML RSS Mobile WAP2