

The short proved to have blown a transistor, which manifested itself in a 100 Ohm resistor getting hot enough to 'smell'. What got me confused initially was that I still had 13.5MHz HF on the output connector. I first replaced the resistor, later I got the correct transistor type and now things are OK. The transistor is apparently part of some feedback circuit (?) that throttles the HF amplitude. The transistor in question is Q1, with a little heatsink, as shown in the detail picture.

For the benefit of others Googling the web for info on fixing their Metcal I have also attached schematics I found on the WWW for the Metcal MX500 base station. That one is different from the RFG-30 but there are enough similarities to make the schematic useful. I never found a RFG-30 schematic unfortunately.

Included are 3 scope screenshots, the first one showing the HF while the generator was broken. The 2nd one shows the HF amplitude during warm up. The 3rd one shows the HF amplitude with the iron idling at it's Curie temperature.

Metcal-MX-500P-11-schematics.pdf (114.87 kB - downloaded 1423 times.)



DSCF2131.JPG (238.88 kB, 1024x768 - viewed 4141 times.)



<mark>H1∿</mark> 20.0V Time 20.00ns 🗰 0.0 metcal\_idling\_at\_curie\_point.jpg (37 kB, 320x234 - viewed 1373 times.)

Freq(1)=13.59MHz Vep(1)= 82.4V

Prd(1)=73.60ns

		Report to mod	lerator 🎛	L Logged
Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #1 on: February 22, 2012, 03:37:03 pm »	Say Thanks	Reply	Quote
	I appreciate the post. I have an RFG-30 that needs repair but I can't to top cover without breaking it. Can you explain the procedure?	figure out how to	remove t	he
	Thanks in advance.			
	Walt			
		Report to mod	lerator 🏓	Logged
wkb Frequent Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Renty #2 on: February 22, 2012, 04:46:48 pm »	Say Thanks	Reply	Quote
	« <b>reply #2 off</b> replacity 22, 2012, 04.40.40 pm #			
	Quote from: whonline on February 22, 2012, 03:37:03 pm			
0110010	I appreciate the post. I have an RFG-30 that needs repair but I can't figure out how breaking it. Can you explain the procedure?	to remove the top cov	er without	
Posts: 540	Thanks in advance.			
	Walt			
	Now remove the Allen head screws from the heat sink. And take the p the heatsink/PCB assy out of the aluminium enclosure. I had to cut a forget to reconnect that on reassembly!	plate that also ha ch will hold it dow plate from the res this time. power inlet out. C (riveted) earth wi	as the ma n. Those t of the u Carefully s ire, don't	hins nit.
		Report to mod	lerator 🏓	L Logged
whonline Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #3 on: February 25, 2012, 06:06:10 pm »	Say Thanks	Reply	Quote
	Your description convinced me the top screws on my unit were hidden the edge, peeled it up and exposed the screws.	by a plastic overl	ay. I four	nd
	My repair was trivial. Hardly a repair at all. I was annoyed by the bur with an LED and am good to go.	ned out light bult	o. I repla	ced it
	Thanks again for your help.			
		Report to mod	lerator 🏓	Logged
Contributor	<ul> <li>Re: Broken Metcal RFG-30 soldering base unit fixed</li> <li>Reply #4 on: April 18, 2012, 12:54:29 am »</li> </ul>	Say Thanks	Reply	Quote
<b>₽ Q</b>	i also have a problem with my metcal			
	Checking the voltage at the 74hct04 inv is only 2.5v , and the rf outp change of electro caps which are over 15 years old etc , doing diode cl showed nothing , and slowly working the schmatic of mx-500 as a gui comparing to the rfg-30 unit , so far with out any success ,	ut is at 3.5mhz , o neck on transistor ide that you have	done the s , and di e here and	norm ode 1
	i have found that the resistance on the board over the q4 is close to do	ead short , even v	vhen the	q4 is

removed , which surprised me , will try replaceing all the transistors if i can with equiv if can as a test , but i am bit lost at this point

if anyone can can verify what the sig / voltage at the test points on the board should be would be very helpfull

What i see at the moment :

- 1. voltage over R1 (100 ohm ) is 20V DOES THIS LOOK CORRECT
- 2. Q1 collector is 6.8v
- 3. R2 via L2 voltage is  $6.8 \nu$  , but on other side of R2 is  $2.5 \nu$  , which is appears wrong
- 4. 74htc04 pin14 vdd = 2.5v, looks wrong

Some input on this would be good guys

Cheers

Sheldon

Sheldon	Report to moderator	🎝 Lo
Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #5 on: April 18, 2012, 05:03:00 am »	Say Thanks Reply	у
Quote from: longpole001 on April 18, 2012, 12:54:29 am		
i also have a problem with my metcal		
Checking the voltage at the 74hct04 inv is only $2.5v$ , and the rf outp caps which are over 15 years old etc, doing diode check on transistor the schematic of mx-500 as a guide that you have here and compari	ut is at 3.5mhz , done the norm change of ele s , and diode showed nothing , and slowly wo ng to the rfg-30 unit , so far with out any suc	ectro orking ccess ,
i have found that the resistance on the board over the q4 is close to d surprised me , will try replacing all the transistors if i can with equiv if	ead short , even when the q4 is removed , wh can as a test , but i am bit lost at this point	hich
if anyone can can verify what the sig / voltage $% \left( {{{\left( {{{\left( {{{\left( {{{\left( {{{\left( {{{c}}}} \right)}} \right.}$	ne board should be would be very helpfull	
What i see at the moment :		
1. voltage over R1 (100 ohm ) is 20V - DOES THIS LOOK CORRECT Don't know, what is voltage on Q1 <b>emitter</b> ?		
2. QI collector is 6.8V The O1 collector is connected to L2 as in #3		
3. R2 via L2 voltage is 6.8v, but on other side of R2 is 2.5v, which is	s appears wrong	
According to the MXP500-11 circuit,D2 ,which is the only 6.8 Volt zene	er on the board is on the opposite side of R2	from
L2, so the voltage on L2 should be higherdifferent circuit?		
Check across D2 to see if it is working.		
4. /4htc04 pin14 vdd = 2.5v , - looks wrong	ator or huffor	
Demiliery wrong, with 2.5 volts on the 74H1C04, you will have no oscill	ator or puner.	

Some input on this would be good guys

Cheers

Sheldon

Report to moderator 🏽 Logged

## Iongpole001

Contributor Posts: 11

Super Contributor

Posts: 4794 Country: 📰 ዲ 🖂 🖵

Re: Broken Metcal RFG-30 soldering base unit fixed	Say Thanks	Reply	Quote
« Reply #6 on: April 18, 2012, 07:12:44 am »			

continue repairs

the 74hct04 is pulling the voltage down . 2.5v , when removed its goes to 8v on pin 14 , after replacing the 74hct04 , it remains at 8v now

output of pin 2 7404 is now 13.5mhz as expected , but the buffered combined outputs of the 7404 which feed Q2 [ VN016n5] ( Q3 on mx500cct) drop to 3.5mhz. and this is reflected at the final stage of output

removing the gate Q2 from the board restores the 13.5hz sig , clearly Q2 has issues

finding that VN0106N5 ( N ch power Mosfet) hard to find - is now been dropped from the supertex product list , and VN0109N5 is also dropped from what i can see, some suppliers on the net show some stock and i am looking to get one.

VN0106N5 - To220 - 60v @2.5A , VN0109N5 - 90v @2.5 , there are many equiv for voltage and current but not many with a @ 5ns turn on / turn off delay time , most mosfets have higher delays typicality about 40ns or more but have greater power output that i have found so far.

if you know of an VN0106N5 equivalent me know ASAP

Also note that if your looking for Q4 - IRF130 - T03 package they are on the net , Q4 on the MX500 shows a IRF 530 on the cct  $\,$  , and its in T0220 package , with same spec's but not fun to retro mount by the looks on RFG-30 heatsink

the repair continues

cheers

		Report to mod	lerator 🕅	- Logged			
Iongpole001 Contributor Posts: 11	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #7 on: April 18, 2012, 08:15:35 am »	Say Thanks	Reply	Quote			
<b>₽ ₽</b>	looking at the possible replacement for VN0106N5 and the IRF510-512	series came up	in searche	es			
	given the input to gate of $13.5  ext{mhz}$ gives a 74ns cycle , half a cycle is	37ns					
	rise half cycle is $=$ turn on delay time + rise time fall half cycle is turn off delay + fall time						
	thus spec for IRF510 -513 series says max rise turn on delay =20ns max rise time =25ns , same for for fall times						
	so half cycle rise time is max 45ns , fall half cycle is 45ns $$ , i need a ma	ıx of 37ns at a fı	req at 13.	5mhz			
	thus this equivilant mosfet wont fit this application						
	am i correct in my calculations ??						
	cheers	Report to more	derator 🏙	Logged			
longpole001 Contributor Posts: 11	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #8 on: April 18, 2012, 10:12:34 am »	Say Thanks	Reply	Quote			
<b>₽</b> .Q	also i find that the irf130 (Q4) spec sheet has over 115ns combined delay + rise time , and 105ns delay + fall time , clearly the gate input is not required to recieve a 13.5mhz signal						
	more like a 4.8mhz given those time of rise and fall specs ( assuming $\mbox{r}$ correct )	ny other calcula	tions are				
	Q4 is driven via the T1 and what looks to be RC filter arrangement look	at Mx500 cct					
	so what is the freq i should expect on the SMA connector for the hand p	iece ??					
	what your thoughts 🧐						
	cheers						
	sheldon	Report to mor	lerator 🎒	logged			
	Des Bushen Materia DEC 20 seldering have			- 209900			
vk6zgo Super Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #9 on: April 18, 2012, 02:49:37 pm »	Say Thanks	Reply	Quote			
Posts: 4794 Country:	I was going to say that the turn on/turnoff specs for use as a switch wo capabilities of the device in linear mode, <b>but</b> looking at the circuit,I can'	uld be worse that t see any biasing	an the 3,so it cert	tainly			

Sup Post Cou 🚨 🖂 🖵

looks like it is being used in a non linear class of operation. If that is so, the filtering (LPF after Q4) is probably just to get rid of any harmonics of 13.5MHz.

C24 is just a coupling capacitor, R27 & R28 constitute a 50 Ohm termination for the secondary of T1. L10 doesn't have any resonating caps--perhaps it is self-resonant at 13.5MHz?

There are no circuit components included that can divide **down** in frequency ,so I suggest that you will still see 13.5MHz at the handpiece in an operational unit. I have seen PowerFets used in "homebrew" Ham Radio transmitters, so that may be somewhere worth looking into. P.S.:Re-read the OPs posting ,it will help more now you have reached this point. « Last Edit: April 18, 2012, 02:57:19 pm by vk6zgo » Report to moderator HL Logged Re: Broken Metcal RFG-30 soldering base 🗆 vk6zgo Say Thanks Reply Quote unit fixed Super Contributor « Reply #10 on: April 18, 2012, 04:22:52 pm » Posts: 4794 Had a look around on Google--doesn't look very hopeful. Country: 🎫 Quite a few designs using switching type Power Fets as RF amps. 🚨 🖂 📿 Almost universally, comments are "low gain", "hard to match, due to high input capacitance", "not much good above 7 MHz", etc. The devices used by Metcal seem to be fairly unusual in having much more useful characteristics at 13.5MHz. Perhaps you need to look at devices originally designed for RF use? 🖺 Logged Report to moderator 🗆 wkb Re: Broken Metcal RFG-30 soldering base Say Thanks Reply Quote unit fixed Frequent Contributor « Reply #11 on: April 18, 2012, 07:16:38 pm » Quote from: vk6zgo on April 18, 2012, 02:49:37 pm I was going to say that the turn on/turnoff specs for use as a switch would be worse than the capabilities of the device in linear mode, but looking at the circuit, I can't see any biasing, so it certainly looks like it is being used in a non linear class of operation Posts: 540 If that is so,the filtering (LPF after Q4) is probably just to get rid of any harmonics of 13.5MHz. Country: 💳 C24 is just a coupling capacitor, R27 & R28 constitute a 50 Ohm termination for the secondary of T1. 💄 🖂 📿 L10 doesn't have any resonating caps--perhaps it is self-resonant at 13.5MHz? There are no circuit components included that can divide down in frequency ,so I suggest that you will still see 13.5MHz at the handpiece in an operational unit. I have seen PowerFets used in "homebrew" Ham Radio transmitters, so that may be somewhere worth looking into. P.S.:Re-read the OPs posting ,it will help more now you have reached this point. The power amp section is class-C, followed by a filter to reduce harmonics. The frequency is 13.5MHz at the handpiece, this is an ISM frequency. Report to moderator <sup>B</sup>Logged Re: Broken Metcal RFG-30 soldering base Joshua Bretz Say Thanks Reply Quote unit fixed Newhie « Reply #12 on: August 30, 2013, 01:56:08 pm » Posts: 1 🚨 📿 Looking at the MX-500 shematic, a short on the gate of Q4 is normal because there is an inductor from gate to source. I found that C24 was blown in my unit which explains why Q1 fried: with C24 blown, this inductor shorts the supply. Replaced C24 with Kemet PHE850ED6100MD18R06L2 and unit works fine. Quote from: longpole001 on April 18, 2012, 12:54:29 am i also have a problem with my metcal Checking the voltage at the 74hct04 inv is only 2.5v, and the rf output is at 3.5mhz, done the norm change of electro caps which are over 15 years old etc , doing diode check on transistors , and diode showed nothing , and slowly working the schmatic of mx-500 as a guide that you have here and comparing to the rfg-30 unit , so far with out any success , i have found that the resistance on the board over the q4 is close to dead short , even when the q4 is removed , which surprised me , will try replaceing all the transistors if i can with equiv if can as a test , but i am bit lost at this point if anyone can can verify what the sig / voltage at the test points on the board should be would be very helpfull What i see at the moment : 1. voltage over R1 (100 ohm ) is 20V - DOES THIS LOOK CORRECT

2. Q1 collector is 6.8v

- 3. R2 via L2 voltage is 6.8v , but on other side of R2 is 2.5v , which is appears wrong
- 4. 74htc04 pin14 vdd = 2.5v , looks wrong

Some input on this would be good guys

Cheers

Sheldon

		Report to mod	erator 🎦	. Logged
<b>mamalala</b>	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #13 on: August 30, 2013, 03:10:24 pm »	Say Thanks	Reply	Quot
and	And just in case:			
S.E.	https://www.eevblog.com/forum/projects/diy-metcal-13-56-mhz-rf-suppl	У		
osts: 777 ountry: 💻	(sorry for the shameless plug)			
$\square \square \square$	Greetings,			
	Chris	Report to mod	erator 賂	. Logged
mamalala	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #14 on: August 30, 2013, 03:19:30 pm »	Say Thanks	Reply	Quo
	Quote from: wkb on December 30, 2011, 11:38:30 pm			
osts: 777	<ul> <li>forgot to put the series cap in the handle on reassembling the cable in this man tuned LC circuit () which did not warm up, not even after the generator was fixed</li> </ul>	de the whole thin ed	g no longer a	а
	I'm curious about that. In the original patent for the handle, there is a ser in my actual RM3-E handles, there is no such cap. It is a straight connecti Talon tweezer i just got also has no series cap.	ries cap mentio ion to the tip c	oned. How artridge. /	ıever, A
	What handle do you have/use? A friend of mine got a newer handle (thos thing with replaceable grips), and no cap in there as well. So unless the R in it's RF output section, i'd say that there is no cap required at all.	e shiny metal/ FG30 is "missi	aluminium ng" some	າ thing
	Greetings,			
	Chris	Report to mod	erator 🏙	. Logged
AndersAnd equent Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #15 on: April 29, 2014, 01:09:59 pm »	Say Thanks	Reply	Quo
sts: 568	Quote from: longpole001 on April 18, 2012, 07:12:44 am			
	finding that VN0106N5 ( N ch power Mosfet) hard to find - is now been dropped from the VN0109N5 is also dropped from what i can see, some suppliers on the net show some sto	supertex produc ock and i am looki	t list , and ng to get on	e.
	VN0106N5 - To220 - 60v @2.5A , VN0109N5 - 90v @2.5 , there are many equiv for volwith a @ 5ns turn on / turn off delay time , most mosfets have higher delays typicality greater power output that i have found so far.	tage and current t about 40ns or mo	out not many re but have	1
	if you know of an VN0106N5 equivalent me know ASAP			
	Also note that if your looking for Q4 - IRF130 - T03 package they are on the net $$ , Q4 or the cct $$ , and its in T0220 package , with same spec's but not fun to retro mount by the l	n the MX500 show ooks on RFG-30 h	s a IRF 530 eatsink	on
	Old topic I know, but I recently came across this topic looking for repair to Metcal MX-500 power supplies. So the below might be useful to others searching for replacements for observer supplies.	ips for a couple solete MOSFET	e of defect s in Metca	t al
	The text is a copy of a reply I made in the <b>DIY Metcal 13.56 MHz RF St</b> https://www.eevblog.com/forum/projects/diy-metcal-13-56-mhz-rf-suppl	<b>Jpply</b> topic: y/msg434497/	′#msg434	497

I've just repaired two MX500 power supplies (won at an eBay auction), with the help of the schematic and documentation here: https://www.mikrocontroller.net/attachment/193474/MX-500P-11.pdf Mirror: http://scopetechniques.com/Metcal/MX-500P-11.pdf

The documentation says: Q3 = VN0109N5 http://scopetechniques.com/Metcal/465-1342-0-VN0109.pdf / http://scopetechniques.com/Metcal/VN0109N5.pdf

Q4 = IRF530(N) http://www.irf.com/product-info/datasheets/data/irf530npbf.pdf

But in the two defect MX500's I bought they were different: Q3 = IRF510 http://www.irf.com/product-info/datasheets/data/irf510pbf.pdf Q4 = IRF640N http://www.irf.com/product-info/datasheets/data/irf640npbf.pdf Both branded International Rectifier.

The amber/orange led lit up all the time in my two defect devices while the green led was always off. I found out Q4 was shorted in both devices and after replacing it with a new IRF640N both devices work again.

It looks like Q3 (IRF510) had been replaced before in at least one of the devices, so not sure if they came with Q3 = IRF510 and Q4 = IRF640N from the factory. But it seems to work, at least so far. Has anyone else seen an MX500 with Q3 = IRF510 and Q4 = IRF640N?

Looks like <u>VN0109N5</u> from Supertex is obsolete, so maybe Metcal started using IRF510 instead? Now when you search <u>Supertex.com</u> VN0109 seems to only be available in wafer / dies and TO-92 housing called <u>VN0109N3</u>, but no TO-220 option.

And for Q4, IRF640N is a 200 V MOSFET, while IRF530(N) from the schematic is only rated at 100 V, so maybe they have replaced it because there was problems with too high voltage spikes, toasting the IRF530's? Doesn't look like IRF530N is obsolete.

Haven't done any measurements after repairing them, so not sure about the voltages Q4 handles? But since the IRF640N was toast in both of them, maybe that's not the issue?

Much to my surprise I also received a Metcal solder stand with the defect power supplies, even though this wasn't advertised. A very nice surprise as Metcal solder stands are actually very expensive and I didn't have any. Later I received a new and very nice MX-H1-AV handpiece as a birthday gift. This came from RS Components where MX-H1-AV seems to be quite cheap compared to many others for some reason, even though RS usually isn't know for being cheap. So if anyone needs a new MX-H1-AV alloy handpiece for your DIY, Metcal or Thermaltronics/Easy Braid power supply, try to check out the price at you national RS Components site.

« Last Edit: April 29, 2014, 01:12:27 pm by AndersAnd »	Report to mod	erator 賂	Logged
Re: Broken Metcal RFG-30 soldering base unit fixed Reply #16 on: April 29, 2014, 09:32:46 pm »	Say Thanks	Reply	Quo
Quote from: mamalala on August 30, 2013, 03:19:30 pm			
Quote from: wkb on December 30, 2011, 11:38:30 pm			
<ul> <li>forgot to put the series cap in the handle on reassembling the cable longer a tuned LC circuit </li> <li>which did not warm up, not even after the</li> </ul>	This made the whole the generator was fixed	iing no	
I'm curious about that. In the original patent for the handle, there is a series cap E handles, there is no such cap. It is a straight connection to the tip cartridge. A series cap.	mentioned. However, in m Talon tweezer i just got als	ny actual RM so has no	13-
What handle do you have/use? A friend of mine got a newer handle (those shiny	metal/aluminium thing wit	h replaceab	le
grips), and no cap in there as well. So unless the RFG30 is "missing" something i is no cap required at all.	n it's RF output section, i'd	say that th	ere
grips), and no cap in there as well. So unless the RFG30 is "missing" something i is no cap required at all. Greetings,	n it's RF output section, i'd	say that th	ere
grips), and no cap in there as well. So unless the RFG30 is "missing" something i is no cap required at all. Greetings, Chris	n it's RF output section, i'd	say that th	ere
grips), and no cap in there as well. So unless the RFG30 is "missing" something i is no cap required at all. Greetings, Chris Falking about a delayed answer Not sure which handle type I have. It sure is an old one, I am prett 1980-1990s.	n it's RF output section, i'd	rom the	ere
grips), and no cap in there as well. So unless the RFG30 is "missing" something i is no cap required at all. Greetings, Chris Falking about a delayed answer Not sure which handle type I have. It sure is an old one, I am prett 1980-1990s.	n it's RF output section, i'd ty sure it dates back f Report to mod	rom the erator	Logged
grips), and no cap in there as well. So unless the RFG30 is "missing" something i is no cap required at all. Greetings, Chris Talking about a delayed answer Not sure which handle type I have. It sure is an old one, I am pretter 1980-1990s. Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #17 on: April 29, 2014, 10:19:16 pm »	n it's RF output section, i'd ty sure it dates back f Report to mod Say Thanks	From the erator	Logged

wkb
 Frequent Contributor



Posts: 540 Country: 💳 ዲ 🖂 🖵

mamalala
 Supporter

Country: 💻

💄 🖂 📿

#### Broken Metcal RFG-30 soldering base unit fixed - Page 1

No worries. As it turns out, there is no cap in there. A friend of mine checked with a network analyzer, and found no hint of a cap being there. Also, the tip detection works by biasing the tip, which in turn requires a DC path, any series cap would make that impossible. This applies to the RM3E handpiece, as well as the newer ones, and also the Talon tweezers, from what i have been able to find out.

Greetings,

Chris

		Report to mod	lerator 🏓	L Logged
AndersAnd Frequent Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #18 on: April 30, 2014, 05:54:53 am »	Say Thanks	Reply	Quote
Posts: 568	Quote from: mamalala on April 29, 2014, 10:19:16 pm			
Country: ==	Quote from: wkb on April 29, 2014, 09:32:46 pm			
	Talking about a delayed answer			
	Not sure which handle type I have. It sure is an old one, I am pretty sure it dates t	back from the 1980-1	990s.	
	No worries. As it turns out, there is no cap in there. A friend of mine checked with a n of a cap being there. Also, the tip detection works by biasing the tip, which in turn rec would make that impossible. This applies to the RM3E handpiece, as well as the newe from what i have been able to find out.	etwork analyzer, and juires a DC path, any r ones, and also the T	found no hi series cap alon tweeze	nt ers,
	Isn't there a feed-through capacitor instead of a series capacitor as we onwards: <a href="https://www.eevblog.com/forum/projects/diy-metcal-13-56-supply/msg310381/#msg310381">https://www.eevblog.com/forum/projects/diy-metcal-13-56-supply/msg310381/#msg310381</a>	talked about ear mhz-rf-	lier from	here
	« Last Edit: May 05, 2014, 06:23:09 pm by AndersAnd »	Report to mod	lerator	L Logged
mamalala	Re: Broken Metcal RFG-30 soldering base unit fixed	Say Thanks	Reply	Quote
	« <b>Reply #19 on:</b> April 30, 2014, 09:22:50 am »			
Posts: 777 Country: 🔤	Isn't there a feed-through capacitor instead of a series capacitor as we talked about e https://www.eevblog.com/forum/projects/diy-metcal-13-56-mhz-rf- supply/msg310381/#msg310381https://www.eevblog.com/forum/projects/diy-metcal supply/msg310381/#msg310381 From what my friend told me, there _seems_ to be none, according to something could have gone wrong, and there is one and he just missed there is also the capacitance from the cable, so that any internal cap w Greetings, Chris	arlier from here onwa I-13-56-mhz-rf- the analyzer. Of o J it, i don't know. 'as simply "hidder	course After all, n" due to	that.
		Report to mod	lerator	L Logged
AndersAnd Frequent Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #20 on: May 05, 2014, 06:20:15 pm »	Say Thanks	Reply	Quote
Posts: 568	Quote from: mamalala on April 30, 2014, 09:22:50 am			
Country: ==	Quote from: AndersAnd on April 30, 2014, 05:54:53 am			
	Isn't there a feed-through capacitor instead of a series capacitor as we talked about <a due="" hidden"="" href="https://www.eevblog.com/forum/projects/diy-metcal-13-56-mhz-rf-supply/msg310381/#msg310381https://www.eevblog.com/forum/projects/diy-metcal-13-56-mhz-rf-supply/msg310381/#msg310381&lt;/a&gt;&lt;/td&gt;&lt;td&gt;It earlier from here on&lt;/td&gt;&lt;td&gt;wards:&lt;/td&gt;&lt;td&gt;&lt;/td&gt;&lt;/tr&gt;&lt;tr&gt;&lt;td&gt;&lt;/td&gt;&lt;td&gt;From what my friend told me, there _seems_ to be none, according to the analyzer. C&lt;br&gt;wrong, and there is one and he just missed it, i don't know. After all, there is also the&lt;br&gt;any internal cap was simply " that.<br="" to="">Greetings, Chris</a>	If course something course something course from the	ould have g cable, so t	one hat

Found these old pics of a disassembled Metcal MX-RM3E https://imgur.com/a/RvDVu#0 They were posted in this topic in Oct. 2012: https://www.eevblog.com/forum/reviews/for-jbc-fansout-there-jbc-tips-anatomy/msg151939/#msg151939

The last pictures shows there actually is a small capacitor in parallel with a  $22\mu H$  inductor.







































1. voltage over R1 (100 ohm ) is 20V - DOES THIS LOOK CORRECT

2. Q1 collector is 6.8v

3. R2 via L2 voltage is 6.8v , but on other side of R2 is 2.5v , which is appears wrong

4. 74htc04 pin14 vdd = 2.5v, - looks wrong

Some input on this would be good guys

Cheers

Sheldon

Joshua what blew your C24 cap? curious!

		Report to mod	lerator	L Logged
hurtmanissimo Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #23 on: February 24, 2017, 07:48:07 pm »	Say Thanks	Reply	Quote
	is possibly to replace VN016n5 Q2 (q3 on mx500) by irf510, but need to schematic) to work properly.	short c20 (mx	:500	
Posts: 6 Country: 💻	without that it start to work on 7mhz 🥹 and very low heating. may be gate capacity irf510 vs VN016n5 make lc-filter like.	different charad	teristics	of
<b>•••</b> ••	hope it will help someone 🥹		Pr-	
		Report to mod	lerator	<b>L</b> Logged
Clauberty	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #24 on: November 04, 2017, 07:54:02 pm »	Say Thanks	Reply	Quote
Country:	Hello			
$\blacksquare \boxtimes Q$	Thank you for the useful post i found here and solved/repaired my mx50	0		
	but i still have one problem, the station does not go off. Meaning green lo me on other station is off, on my station will remain on has long has the	ed after 30 min switch is ON	measure	ed by
	yes there is a little torx / hex screw on the side of the station and it is sc activated, has is on the station that this standby of is working	rewed in so sw	itch is	
	i made the testing with the same Hand Piece and Work-stand from the li	nk		
	https://gokimco.com/oki-mfr-uk1-cartridge-hand-piece-and-workstand.h	itml		
	Thank you		Dia.	
	« Last Edit: November 04, 2017, 07:58:18 pm by clauberty »	Report to mod	lerator	<b>L</b> Logged
Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #25 on: November 07, 2017, 11:53:11 pm »	Say Thanks	Reply	Quote
Country: III Log Q	Hello I've got Metcal MX-5200 not heating up the tip at all. Main MOSFET Q14 IXFH12N50F is getting very hot only when iron connec Checked all diodes and caps around. U4 LM2576HVT gives on output 45V all time when iron is connected. U3 LM2574HVM gives on output 5V all time when iron is connected. Vcc 5.69V on 74hc04	cted.		
	Any ideas what can be wrong? Regards			
	« Last Edit: November 09, 2017, 02:30:52 pm by memed »	Report to mod	lerator 🏓	l Logged
fireworks Contributor Poster: 25	<ul> <li>Re: Broken Metcal RFG-30 soldering base unit fixed</li> <li>« Reply #26 on: November 08, 2017, 07:20:15 am »</li> </ul>	Say Thanks	Reply	Quote
Country:	Can you post a picture of the board ?			
<b>₩</b> ₩Ψ	Do you have a schematic ?	Report to mod	lerator	<b>l</b> Logged
memed     Contributor	Re: Broken Metcal RFG-30 soldering base unit fixed	Say Thanks	Reply	Quote

Broken Metcal RFG-30 soldering base unit fixed - Page 1 Posts: 5 « Reply #27 on: November 08, 2017, 11:37:03 am » Country: 🔡 💄 🖂 📿 I don't have schematic for MX-5200 or even MX-5000. I found online only schematic for MX-500p-11 but looks to different for me I will post pictures of the board front and back on evening. LM2576HVT gives Uout-45V with feedback-0.8V is it correct? Report to moderator Logged Re: Broken Metcal RFG-30 soldering base □ fireworks Ø Say Thanks Quote Reply unit fixed Contributor « Reply #28 on: November 08, 2017, 01:24:08 pm » Posts: 35 Country: 🔯 I'll help you repair it. 💄 🖂 📿 Do you have an oscilloscope ? 1. First please post pictures of the front and back of the board. 2. If you have an oscilloscope, please post the waveforms at the 3 terminals of the output MOSFET right after powering up the station - the handle needs to be connected to the station and a known good tip must be in the handle. Report to moderator HL Logged Re: Broken Metcal RFG-30 soldering base memed Say Thanks Reply Quote unit fixed Contributor « Reply #29 on: November 09, 2017, 12:47:35 am » Posts: 5 Country: 🔡 Thanks, really appreciate Fireworks. 🚨 🖂 📿 Unfortunatelly I don't have an oscilloscope but still hoping can manage some how 🙆 When I put a probe on output MOSFET then DMM geting crazy and switching off. All my tips and handle are 100% working. 74HC04N PIN 8- IN - 2.09V PIN 9- OUT - 3.80V PIN 14 - 5.69V U4 - LM2576HVT IN - 48V OUT - 45V Q13 IRF510 DRAIN - 26V Q14 IXFH12N50F DRAIN - UNREADABLE BY DMM Board pictures







### □ fireworks

Contributor Posts: 35 Country: Country:

Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #30 on: November 10, 2017, 03:06:21 am »	Say Thanks	Reply	Quote

Without oscilloscope is more difficult to fix it, but still doable.

1. The board is not too complex. Can you reverse engineer it and draw the schematics ? Shouldn't take more than a few hours.

2. Without oscilloscope, you need to build a RF voltmeter. It's very simple, 3-4 diodes 1N4148 in series, a 1M resistor and a ceramic capacitor of tens of nF.

3. First step: unsolder the output MOSFET and check it with a multimeter.

Also, measure the voltages at its 3 pins while unsoldered.

If your multimeter has a frequency meter, measure the frequency (and duty cycle if available) at the gate of the unsoldered MOSFET.

Report to moderator 🏽 💾 Logged



Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #31 on: November 13, 2017, 10:48:52 pm »

https://www.eevblog.com/forum/projects/broken-metcal-rfg-30-soldering-base-unit-fixed/?all

Say Thanks Reply Quote

Posts: 5 Country: 🚟	I'm looking to buy some good oscilloscope as it will help me to fix more d	levices and get	experien	ce 😬
🚨 🖂 🖓	Thanks to you now and will be back later to get it sorted	-		
		Report to mode	erator 🎮	. Logged
	🔿 Re: Broken Metcal RFG-30 soldering base			
	unit fixed	Say Thanks	Reply	Quote
Posts: 5	« <b>Reply #32 on:</b> January 10, 2018, 09:38:10 am »			
Country: 🔤	Hello Fireworks,			
₽	Can I ask what the voltage output of U4 on pin2?			
	Thank you.			
		Report to mod	erator P <sup></sup> L	. Logged
🗆 fireworks	🔊 Re: Broken Metcal RFG-30 soldering base			
Contributor	unit fixed	Say Thanks	Reply	Quote
Posts: 35	« <b>Reply #33 on:</b> January 11, 2018, 07:28:40 am »			
Country:	Hi,			
$\mathbb{Z}$ $\boxtimes$ $\bigcirc$				
	I don't have the voltage. Are you trying to do a repair?	B I I I	. Bh	1
		Report to mod	erator 📲	. Logged
🗆 lanuser	🔊 Re: Broken Metcal RFG-30 soldering base			_
Contributor	winit fixed	Say Thanks	Reply	Quote
Posts: 5	« <b>Reply #34 on:</b> January 12, 2016, 05:52:22 and »			
Country: 🔤	Yes, I am trying to repair my Metcal station.			
$\sim$		Report to mod	erator 🎘	Logged
	Dec Decker Materia DEC 20 caldering have			
fireworks	unit fixed	Say Thanks	Reply	Quote
	« Reply #35 on: January 12, 2018, 02:12:46 pm »			
Country:	I can beln you with your repair but I need more details			
$\mathbb{A} \boxtimes \mathbb{Q}$	1. Which Metcal station do you have ?			
	2. What are the symptoms ?			
	<ol> <li>What did you measure so far ?</li> <li>What equipment do you have ? An oscilloscope will be very useful but '</li> </ol>	you can do with	nout.	
		Report to mod	erator 🎦	. Logged
🗆 lanuser	Re: Broken Metcal RFG-30 soldering base	Say Thanks	Reply	Quote
Contributor	« <b>Reply #36 on:</b> January 12, 2018, 08:15:19 pm »			
Posts: 5 Country: 🔤				
<b>a</b> Q <sup>´</sup>	<ol> <li>Which Metcal station do you have ? (Metcal Model# mx-500p-11)</li> <li>What are the symptoms ? (LM2576 U4 burned out)</li> </ol>			
	3. What did you measure so far ? ( U4 showing sign of burned marks )			
	4. What equipment do you have ? An oscilloscope will be very useful but	you can do with	nout. (	
	Until I receive U4 replacement part I was trying to use external power su	upply replicating	g U4 volta	age
	Thank you.	i belole.		
		Depart to med	erator 👪	Logged
		κεροιτ το 1100		. Loggea
🗆 fireworks	🔊 Re: Broken Metcal RFG-30 soldering base	Cov. The 1	Dent	0
Contributor	<b>unit fixed</b>	Say Thanks	керіу	Quote
Posts: 35	« керіу #Э7 он. January 14, 2010, 10.37.49 ані » 			
Country: 🛄	Since you have a Mx-500p-11, it should be easy to repair since the sche	ematics is availa	able.	
	Can you post some pictures of the board ? Regarding the voltage: the real value is not important. You can the uping	10-20\/ with a	urrent lin	nitina
	to 1A for example.	יי 200 Willi C	an cht III	inting
	Since U4 burned, there might be shorts in the rest of the circuit. Even b	efore connectin	ig a powe	r
	supply in place of 04, you should check the components "downstream" fr « Last Edit: January 14, 2018, 11:14:17 am by fireworks »	UIII U4.		Law 11
	,,,,,,,,,	Keport to mod	erator 📲 L	Logged

🗆 lanuser

Contributor Posts: 5 Country: 🖼

🗆 Wolfram

Regular Contributor
Posts: 118
Country:

Contributor
Posts: 5
Country:

Wolfram
 Regular Contributor

Posts: 118

<u>\_</u>Q

<u>\_</u>Q

Country: 🔚

miked
 Newbie
 Posts: 1
 Country:

Re: Broken Metcal RFG-30 soldering base unit fixed	Say Thanks	Reply	Quote
I have checked for short of the circuit prior to replacement U4 IC. After replacing U4 everything went back to normal, however, I would full 100% functionality.	like to properly ad	just static	on to
I will appreciate all the help I can get. Thank you.			
	Report to mod	lerator 🕅	. Logged
Re: Broken Metcal RFG-30 soldering base unit fixed « Reply #39 on: January 17, 2018, 10:27:34 pm »	Say Thanks	Reply	Quote
As this is the currently active thread on Metcal repair, I'll add a story concern the RFG-30 but the MX-500p-21.	here, even if it doe	esn't direc	tly
be operating correctly. The feedback signal to the LM2576 was at 1.2 in regulation, but that the output stage was delivering much less pow	3 V, hinting that th	e RF loop	was
buck converter to compensate. The gate Waveform of Q4 looked reas stage voltage is derived from the buck converter output, so this was output voltage) but drain waveform was a mess, with a significant os MHz operating frequency. I measured all the passives in the matching measured within tolerance, except for C27 (130 pf silver mica) which from a second broken MX-500p-21, and measuring it before installing tolerance at 45 pF. C28 (which is identical to C27 and connected direc in both units. Replacing C27 in the first unit with C28 from the second operation, with the output stage supply voltage within the normal rar unit had the same fault, so this might be a common problem. It is pro C27 and C28 in MX-500s with blown output or driver stage transistors them are out of tolerance.	ionable, if a little hi a symptom of the h cillation at four tim g network, and all of measured 60 pF. I g it showed that it v ctly in parallel) mea d unit restored it to nge. It appears that obably a good idea s, and to replace bo	gh (the di nigh buck les the 13 componen borrowec was also o asured spo o normal t the seco to measu oth if any	ne river .56 its d C27 out of ot on nd ire of
buck converter to compensate. The gate waveform of Q4 looked reas stage voltage is derived from the buck converter output, so this was output voltage) but drain waveform was a mess, with a significant os MHz operating frequency. I measured all the passives in the matching measured within tolerance, except for C27 (130 pf silver mica) which from a second broken MX-500p-21, and measuring it before installing tolerance at 45 pF. C28 (which is identical to C27 and connected direc in both units. Replacing C27 in the first unit with C28 from the second operation, with the output stage supply voltage within the normal rar unit had the same fault, so this might be a common problem. It is pr C27 and C28 in MX-500s with blown output or driver stage transistors them are out of tolerance.	ionable, if a little hi a symptom of the h cillation at four tim g network, and all of measured 60 pF. I g it showed that it w ctly in parallel) mea d unit restored it to nge. It appears that obably a good idea s, and to replace bo	gh (the di nigh buck les the 13 componen borrowed was also o asured spo o normal t the seco to measu oth if any	ne river .56 its d C27 but of ot on nd ire of they
buck converter to compensate. The gate waveform of Q4 looked reas stage voltage is derived from the buck converter output, so this was output voltage) but drain waveform was a mess, with a significant os MHz operating frequency. I measured all the passives in the matching measured within tolerance, except for C27 (130 pf silver mica) which from a second broken MX-500p-21, and measuring it before installing tolerance at 45 pF. C28 (which is identical to C27 and connected direc in both units. Replacing C27 in the first unit with C28 from the second operation, with the output stage supply voltage within the normal rar unit had the same fault, so this might be a common problem. It is pre C27 and C28 in MX-500s with blown output or driver stage transistors them are out of tolerance. Next up is a pair of MX-PS5000s with the same symptom; dead buck work for a short time before the regulator fails again. <i>« Last Edit: January 17, 2018, 10:31:01 pm by Wolfram »</i>	ionable, if a little hi a symptom of the h cillation at four tim g network, and all of measured 60 pF. I g it showed that it w ctly in parallel) mea d unit restored it to nge. It appears that obably a good idea s, and to replace bo regulator. After reg	gh (the di nigh buck les the 13 componen borrowed was also d asured spo o normal t the seco to measu oth if any blacing it,	ne river .56 its d C27 out of ot on nd ire of they .Logged
buck converter to compensate. The gate waveform of Q4 looked reas stage voltage is derived from the buck converter output, so this was output voltage) but drain waveform was a mess, with a significant os MHz operating frequency. I measured all the passives in the matching measured within tolerance, except for C27 (130 pf silver mica) which from a second broken MX-500p-21, and measuring it before installing tolerance at 45 pF. C28 (which is identical to C27 and connected direc in both units. Replacing C27 in the first unit with C28 from the second operation, with the output stage supply voltage within the normal rar unit had the same fault, so this might be a common problem. It is pr C27 and C28 in MX-500s with blown output or driver stage transistors them are out of tolerance. Next up is a pair of MX-PS5000s with the same symptom; dead buck work for a short time before the regulator fails again. <i>« Last Edit: January 17, 2018, 10:31:01 pm by Wolfram »</i>	ionable, if a little hi a symptom of the h cillation at four tim g network, and all of measured 60 pF. I g it showed that it w ctly in parallel) mea d unit restored it to nge. It appears that obably a good idea s, and to replace bo regulator. After rep Report to mod	gh (the di nigh buck les the 13 componen borrowed was also o asured spo o normal t the seco to measu oth if any blacing it,	ne river .56 its d C27 out of ot on nd ire of they . Logged
buck converter to compensate. The gate waveform of Q4 looked reas stage voltage is derived from the buck converter output, so this was output voltage) but drain waveform was a mess, with a significant os MHz operating frequency. I measured all the passives in the matching measured within tolerance, except for C27 (130 pf silver mica) which from a second broken MX-500p-21, and measuring it before installing tolerance at 45 pF. C28 (which is identical to C27 and connected direc in both units. Replacing C27 in the first unit with C28 from the second operation, with the output stage supply voltage within the normal rar unit had the same fault, so this might be a common problem. It is pre C27 and C28 in MX-500s with blown output or driver stage transistors them are out of tolerance. Next up is a pair of MX-PS5000s with the same symptom; dead buck work for a short time before the regulator fails again. « <i>Last Edit: January 17, 2018, 10:31:01 pm by Wolfram</i> » <b>The following users thanked this post:</b> helius, lanuser <b>Re: Broken Metcal RFG-30 soldering base</b> unit fixed « <b>Reply #40 on:</b> January 18, 2018, 06:24:08 pm »	sonable, if a little hi a symptom of the h cillation at four tim g network, and all of measured 60 pF. I g it showed that it v ctly in parallel) mea d unit restored it to nge. It appears that obably a good idea s, and to replace bo regulator. After reg Report to mod Say Thanks	gh (the di nigh buck less the 13 componen borrowed was also o asured spo o normal t the seco to measu oth if any blacing it, lerator	ne river .56 its d C27 out of ot on nd ire of they . Logged
buck converter to compensate. The gate Waveform of Q4 looked reas stage voltage is derived from the buck converter output, so this was output voltage) but drain waveform was a mess, with a significant os MHz operating frequency. I measured all the passives in the matching measured within tolerance, except for C27 (130 pf silver mica) which from a second broken MX-500p-21, and measuring it before installing tolerance at 45 pF. C28 (which is identical to C27 and connected dired in both units. Replacing C27 in the first unit with C28 from the second operation, with the output stage supply voltage within the normal rar unit had the same fault, so this might be a common problem. It is pri C27 and C28 in MX-500s with blown output or driver stage transistor: them are out of tolerance. Next up is a pair of MX-PS5000s with the same symptom; dead buck work for a short time before the regulator fails again. « <i>Last Edit: January 17, 2018, 10:31:01 pm by Wolfram</i> » <b>The following users thanked this post:</b> helius, lanuser <b>Re: Broken Metcal RFG-30 soldering base</b> unit fixed « Reply #40 on: January 18, 2018, 06:24:08 pm »	ionable, if a little hi a symptom of the h cillation at four tim g network, and all of measured 60 pF. I g it showed that it v ctly in parallel) mea d unit restored it to nge. It appears that obably a good idea s, and to replace bo regulator. After rep Report to mod Say Thanks	gh (the di nigh buck les the 13 componen borrowed was also o asured spo o normal t the seco to measu oth if any blacing it, lerator	ne river .56 its d C27 out of ot on nd ire of they . Logged Quot
buck converter to compensate. The gate waveform of Q4 looked reas stage voltage is derived from the buck converter output, so this was output voltage) but drain waveform was a mess, with a significant os MHz operating frequency. I measured all the passives in the matching measured within tolerance, except for C27 (130 pf silver mica) which from a second broken MX-500p-21, and measuring it before installing tolerance at 45 pF. C28 (which is identical to C27 and connected direc in both units. Replacing C27 in the first unit with C28 from the second operation, with the output stage supply voltage within the normal rar unit had the same fault, so this might be a common problem. It is pr C27 and C28 in MX-500s with blown output or driver stage transistor: them are out of tolerance. Next up is a pair of MX-PS5000s with the same symptom; dead buck work for a short time before the regulator fails again. « <i>Last Edit: January 17, 2018, 10:31:01 pm by Wolfram</i> » <b>The following users thanked this post:</b> helius, lanuser <b>W</b> <b>Re: Broken Metcal RFG-30 soldering base</b> <b>unit fixed</b> <b>Reply #40 on:</b> January 18, 2018, 06:24:08 pm » Do you know by any chance, how much difference in the schematic b 500p-11?	ionable, if a little hi a symptom of the h cillation at four tim g network, and all of measured 60 pF. I g it showed that it w cttly in parallel) mea d unit restored it to nge. It appears that obably a good idea s, and to replace bo regulator. After rep Report to mod Say Thanks retween MX-500p-2 Report to mod	gh (the di nigh buck les the 13 componen borrowed was also o asured spro- o normal t the seco to measu oth if any blacing it, lerator a Reply	ne river .56 its d C27 out of ot on nd ire of they . Logged

As far as I know, the only difference is the default configuration of the supply transformer primary wiring, the -11 is configured for 115 V and -21 is configured for 230 V. Either can be changed to the other by moving a few solder jumpers on the board.

Re: Broken Metcal RFG-30 soldering base unit fixed	Say Thanks	Reply	Quote
« Reply #42 on: January 20, 2018, 07:27:58 pm »			

I made a successful repair of a STSS-002 model RFG-30 Serial 6011xxx This version has two diffused T 1 3/4 LEDs installed, one Green (power) one Red (RF lockout) There appears to be \*many\* versions of this excellent soldering system, all with minor differences and component changes.

The hard part: take the screws out of the top and disconnect the insulated power connectors. The

Report to moderator 🏽 Logged

two 1/4" quick connects to the mains transformer are a pain. (a lot of wiggling needed, these were very tight !)

Now, you can drop the bottom and remove the power transformer after desoldering the ground lead from the case lug.

Q1, the ZTX749 PNP with small round heatsink, had a collector to emitter short. I suspect the heatsink does not make good thermal contact in this application, and might be something to watch for. As I didn't have anything like this in the junk box, I used a On Semi NSS60600MZ4T1G from a sample kit (price was right, and was a lower VCE(sat) than the original part) The kit included small surf boards with copper heatsink islands. I wired the eval board in vertically with respect to the case with clippings from some capacitor thru hole leads. I had to be careful not to let the small board extend up above the main board edge, so it fit back in the case. I ended up trimming the ON semi supplied eval board a bit. If I did this again, I would have clipped that Q1 out, and removed the leads one by one, because the main board was thermal damaged either by me or by the failed transistor, and I lifted a pad. Oh well.

Unfortunately, that was not all that was wrong. Old corroded solder flux on a tiny glued in sub board kept the unit in the two LED illuminated RF lockout state. I think this board just puts a small DC bias on the tip, and locks out RF if there is an intermittent connection to the wand (bad wand detector) It simply needed the connections re heated and the old flux removed with 91% isopropyl alcohol. After verifying, I used GE silicone II to attach the two sub boards back to the main board. I held them in place with tape overnight for a full cure.

I do wonder how long these electrolytic capacitors will last. My unit was made around 1990. I additionally soldered a 0.1uF 100V disc across the 1000uF Capacitor on the top of the board (this feeds the RF lockout board) and put a 1000pF disc between the collector of Q1 to ground to bleed off any stray RF created with that wing board. Seems to work fine now.

Report to moderator Logged

Pages: 1 2 [All] Go Up	REPLY	NOTIFY	MARK UNREAD	SEND THIS TOPIC	PRINT	SEARCH
					« prev	vious next »
Share me						



EEVblog Electronics Community Forum » Electronics » Projects, Designs, and Technical Stuff » Broken Metcal RFG-30 soldering base unit fixed

LINK TO CALENDAR







**EEVblog Main Site** 

EEVblog on Youtube

EEVblog on Twitter

EEVblog on Facebook

QOUTE NOW

SMF 2.0.15 | SMF © 2017, Simple Machines Simple Audio Video Embedder SMFAds for Free Forums XHTML RSS Mobile WAP2