

Keithley Instruments
28775 Aurora Road
Cleveland, Ohio 44139
1-800-833-9200
tek.com/keithley

CONTENTS

General Information	3
Supported Models	3
Installation Instructions	3
Version 1.7.12 Release	4
Overview	4
Critical Fix	4
Version 1.7.10 Release	5
Overview	5
Critical Fixes	5
Enhancements	6
Version 1.7.7 Release	6
Overview	6
Critical Fixes	6
Version 1.7.5 Release	7
Overview	7
Critical Fixes	7
Enhancements	7
Version 1.7.3 Release	7
Overview	7
Critical Fixes	7
Enhancements	8
Version 1.7.2 Release	9
Overview	9
Critical Fixes	9



Noncritical Fixes 9

Version 1.7.1 Release 9

 Overview..... 9

 Critical Fixes 9

 Enhancements..... 10

Version 1.7.0 Release 10

 Overview..... 10

 Critical Fixes 10

 Known Issues 11

 Enhancements..... 12

Version v1.6.8b Release 14

 Overview..... 14

 Enhancement 14

 Noncritical Fix..... 14

Version v1.6.7c Release 15

Version v1.6.4c Release 20

Version v1.6.3d Release 21

Version v1.6.1a Release 23

Version v1.6.0i Release 24

Version v1.5.0g Release 29

Version v1.3.0s Release 33

Version v1.2.0f Release 42

Version v1.1.0s Release 47

Version v1.0.0i Release 59

GENERAL INFORMATION

SUPPORTED MODELS

This firmware is used on the following Keithley Instruments product models:

Model 2450 Interactive SourceMeter® Instrument, 2450-NFP, 2450-RACK, 2450-NFP-RACK



***** ATTENTION CRITICAL ATTENTION CRITICAL ATTENTION CRITICAL *****

If you are upgrading your firmware from version 1.0.0i, you must run the upgrade two times.

INSTALLATION INSTRUCTIONS

Firmware upgrade and downgrade instructions

NOTE

If you are upgrading from a firmware version earlier than 1.7.10, use the **Downgrade to older** option from the front panel or use the downgrade remote commands. See "Upgrading the firmware" in your instrument's Reference Manual for more information. When upgrading from a firmware version earlier than 1.7.10, system messages will display the firmware version as 1.7.1. This is a cosmetic issue and does not affect instrument performance.

If you are upgrading your instrument from version 1.7.10, follow the "Installation Instructions" in the **General Information** section of this document.

CAUTION

Do not turn off power or remove the USB flash drive until the upgrade process is complete.

From the front panel:

1. Copy the firmware upgrade file (.upg file) to a USB flash drive.
2. Verify that the upgrade file is in the root subdirectory of the flash drive and that it is the only firmware file in that location.
3. Disconnect any terminals that are attached to the instrument.
4. Turn the instrument power off. Wait a few seconds.
5. Turn the instrument power on.
6. Insert the flash drive into the USB port on the front panel of the instrument.
7. From the instrument front panel, press the **MENU** key.
8. Under System, select **Info/Manage**.
9. Choose an upgrade option:
 - To upgrade to a newer version of firmware: Select **Upgrade to New**.
 - To return to a previous version of firmware: Select **Downgrade to Older**.
10. When the upgrade is complete, reboot the instrument.

A message is displayed while the upgrade is in progress.

For additional firmware installation instructions, refer to the "Upgrading the firmware" topic in the "Maintenance" section of the *Model 2450 Interactive SourceMeter Instrument Reference Manual* (document number 2450-901-01). This manual is available online at tek.com/keithley.

VERSION 1.7.12 RELEASE

OVERVIEW

Version 1.7.12 provides a fix.

CRITICAL FIX

Reference number:	NS-2105
Symptom:	Saving numerous configuration scripts or system setups may lead to an out of memory error message depending on the time since the instrument has been restarted.
Resolution:	This issue has been resolved.

VERSION 1.7.10 RELEASE

NOTE

When you load the 1.7.10 firmware into your instrument, system messages will display the firmware version as 1.7.1. This is only a cosmetic issue and does not impact the performance of the unit. Subsequent firmware upgrades will display a two-digit firmware version number.

To install firmware version 1.7.10 on your instrument, use the **Downgrade to older** option from the front panel or use the downgrade remote commands. See "Upgrading the firmware" in your instrument's Reference Manual for more information.

OVERVIEW

Version 1.7.10 provides fixes and enhancements.

CRITICAL FIXES

Reference number:	NS-2070
Symptom:	Heavy script processing can interfere with the timely generation of an SRQ as the result of setting the MAV bit in the Status Byte Register. This interference affects both the bus and the front panel display.
Resolution:	This issue has been resolved.
Reference number:	NS-2072
Symptom:	After changing the group number of a node to be the group number previously used for another node, the instrument may generate errors when trying to start a test on that node using the <code>execute()</code> command, even after using <code>waitcomplete()</code> to make sure the previous tests have finished. Subsequently, performing a <code>waitcomplete()</code> on the previous group number may cause the instrument to wait for tests to complete on that node even though the node is in a new group.
Resolution:	This issue has been resolved.
Reference number:	NS-2074
Symptom:	The MAV bit may be set in the status byte indicating that there is data to be read from the instrument, but the subsequent read operation to pull that data from the instrument fails and times-out. This may occur when rapidly generating data and enabling the MAV bit to be set in the status model to indicate when data is available to read from the instrument.
Resolution:	This issue has been resolved.

ENHANCEMENTS

Category:	System commands
Reference number:	NS-1946
	New commands have been added:
	TSP: lan.dstprotection = lan.ON or lan.OFF
	SCPI: SYSTem:COMMunication:LAN:DST:PROTection <ON (1) or OFF (0)>
	OFF is the default command state.
	When DST protection is turned OFF, a simple open-and-close on the DST port (5030) will close any and all open LAN connections.
	When DST protection is turned ON, the DST port will need to be opened and the system login and password entered followed by closing the DST port to close any open LAN connections, including the DST port.
	Turning DST protection ON prevents LAN connections from being inadvertently closed by your IT department performing a port scan across the corporate network.

VERSION 1.7.7 RELEASE**OVERVIEW**

Version 1.7.7 provides fixes.

CRITICAL FIXES

Reference number:	NS-2025
Symptom:	While running a test loop in an application that sends the <code>reset()</code> command as part of the code, a blue screen appears after running the test for several days.
Resolution:	The issue has been resolved.
Reference number:	NS-2043
Symptom:	While remotely communicating with the instrument, if a new error is displayed on the front panel shortly after a previous error is being cleared from the front panel, the instrument may become unresponsive or inoperative.
Resolution:	The issue has been resolved.

VERSION 1.7.5 RELEASE

OVERVIEW

Version 1.7.5 provides fixes and enhancements.

CRITICAL FIXES

Reference number:	NS-1978
Symptom:	Unable to set voltage protection level with the SCPI command <code>SOUR:VOLT:PROT:LEV</code> and query the setting when the source function is set to current.
Resolution:	This issue has been resolved.
Reference number:	NS-1981
Symptom:	When measuring in local mode with sense mode set to 4-wire or output off mode set to High Z, and turning output on, measurement readings do not automatically begin. Instead, you must turn continuous measurements on manually after turning the output on.
Resolution:	The issue has been resolved to automatically start continuous measurements in these configurations.

ENHANCEMENTS

Category:	General settings
Reference number:	The "Branch to Block" setting on various branch blocks on the Trigger Flow screen on the front panel now allows a minimum value of 0.

VERSION 1.7.3 RELEASE

OVERVIEW

Version 1.7.3 provides fixes and enhancements.

CRITICAL FIXES

Reference number:	NS-1923
Symptom:	When measuring resistance in local mode, the SMU does not switch from <code>INACTive</code> to <code>CONTinuous</code> measurement when output is turned on.
Resolution:	This issue has been corrected.
Reference number:	NS-1927
Symptom:	The LXI identification web page shows the incorrect LXI version and web page links.
Resolution:	This issue has been corrected.

Reference number:	NS-1944
Symptom:	Source and Limit values do not update correctly when exiting the quick edit method (not live edit) with the navigation control.
Resolution:	This issue has been corrected.

ENHANCEMENTS

Category	Remote commands
Reference number:	<p>NS-1931: Added a TLS (transport layer security) option when using the <code>tspnet.connect()</code> command.</p> <pre>connectionID = tspnet.connect(ipAddress, portNumber, initString, useTLS)</pre> <p><i>ipAddress</i>: A string that indicates the IP address or host name to connect to. <i>portNumber</i>: Default 5025. <i>initString</i>: Sends a string to <i>ipAddress</i>. <i>useTLS</i>: 0 or 1; 0: Do not use TLS with the connection (default) 1: Use TLS with the connection.</p> <p>When <i>useTLS</i> is set to 1, the instrument negotiates the security protocol when connecting to the host or IP address that is used. This security protocol is used when using <code>tspnet.write()</code> to send data or <code>tspnet.read()</code> to receive data.</p> <p>The following is an example of how to use a host name with the TLS option:</p> <pre>connectionID = tspnet.connect("hostname.domain.com", 443, "", 1)</pre>
Category	Remote commands
Reference number:	<p>NS-1960: The <code>localnode.gettimewithfractional()</code> TSP command is available to retrieve the number of seconds elapsed since January 1, 1970, with fractional seconds appended to the returned response.</p>

VERSION 1.7.2 RELEASE

OVERVIEW

Version 1.7.2 provides fixes and required support.

CRITICAL FIXES

Reference number:	NS-1902
Symptom:	After using a pulse or sweep command that specifies a user-created buffer instead of a default buffer, the configuration of the instrument is saved in a setup or configuration script. Recalling this setup or running this script causes an error that says a parameter expecting a certain reading buffer type but instead finding an unknown type.
Resolution:	This issue has been corrected.

NONCRITICAL FIXES

Reference number:	NS-1915
Symptom:	When running a Test Script Processor® (TSP) script application with a custom user interface that has an End App button, the custom user interface may not close properly when “End App” is selected.
Resolution:	This issue has been corrected. This fix also introduces a behavior change from previous firmware versions. If you are running a nested script (scripts running within a script), the user interface only displays the first running script. Previously, the user interface displayed name changes between nested scripts.

VERSION 1.7.1 RELEASE

OVERVIEW

Version 1.7.1 provides minor fixes and required support for the I-V Tracer TSP™ Application. You must install the new firmware to use the Application, available from:

https://www.tek.com/en/keithley-i-v_tracer.

The support changes for the Application do not impact normal instrument operation.

CRITICAL FIXES

Reference number:	NS-1846
Symptom:	Pressing the Function key repeatedly while running a script or trigger model generates several messages stating that the key is disabled. This may cause the instrument to stop functioning, depending on the number of messages generated.
Resolution:	This issue has been corrected.

ENHANCEMENTS

Category	Applications
	<ul style="list-style-type: none"> Changes have been made to the Apps Manager view to state whether or not an Application is supported on an instrument and the required firmware version.

VERSION 1.7.0 RELEASE

OVERVIEW

Version 1.7.0 is a significant maintenance firmware release for the 2450 that provides numerous updates along with stability and reliability improvements. See the *Model 2450 Interactive SourceMeter Instrument Reference Manual* (document number 2450-901-01) for more information.

CRITICAL FIXES

Reference number:	AR41304, NS-460
Symptom:	Unable to set continuous measurement with a remote command.
Resolution:	Remote commands added.
Reference number:	AR41750, AR41769, AR42131, AR42243, AR42807, AR50058, AR50059, NS-422
Symptom:	<p>The effective source limit of the SMU is the lesser of either the programmed source limit or 105% of the active measure range. If you use fixed measure ranges, the instrument prevents you from selecting different limit and measure ranges.</p> <p>However, if measure autorange is selected, it is possible for the autorange process to cause the ranges to differ because the instrument may go down to a range that is lower than the one on which the source limit is programmed. This causes the effective source limit to drop to 105% of the newly selected measure range. The source limit will remain at this value until either you make another measurement that causes a range change or you explicitly select another range.</p> <p>If you take no action to change the measure range before you change the source level, or perhaps test a new device, you may find that the output voltage or current level is less than expected due to the reduced source limit. This may prevent your device from properly turning on or otherwise operating as expected.</p>
Resolution:	These issues have been addressed. The front panel display now indicates if the SMU output is limited by the programmed source limit or by the active measure range. A new autorange mode was added to automatically set the measure range equal to the source limit range after a measurement is completed (see "Enhancements").

Reference number:	AR55036, AR62150, NS-339
Symptom:	Repeated creation and deletion of user-defined buffers may cause out-of-memory errors. Error messages indicating the maximum size for buffers being created are wrong and provide misleading guidance.
Resolution:	Reading buffer memory management now allows users to easily allocate the largest size available when creating a reading buffer. Documentation has been clarified to explain the creation process. Improved buffer memory management also greatly reduces the possibility of getting out-of-memory errors.
Reference number:	AR56349, AR60259, NS-929
Symptom:	USB communication issues.
Resolution:	To better accommodate the variety of VISA installation options available to users, the STALLing USBTMC is not active as it had been before.
Reference number:	AR61116, AR62660, NS-529, NS-1558
Symptom:	Repeatedly saving a buffer to a file on a USB flash drive using the <code>buffer.saveappend</code> command eventually causes Error 2203, "Cannot open file."
Resolution:	This issue has been corrected.
Reference number:	AR62310
Symptom:	Exercising various combinations of front panel settings for the Event Log may cause the front panel to lock up.
Resolution:	This issue has been corrected.
Reference number:	AR63189
Symptom:	The 2450 is configured for both source and measure autoranging. Forward bias tests of a Zener diode are performed by applying 2 V with a 1 A source limit. The SMU reaches the 1 A limit as expected. After turning off the output, the source level is changed to -1 V and the source limit is changed to 100 uA. When the output is turned on and the reverse bias tests are performed, the SMU does not downrange as expected, and it incorrectly indicates that it is limiting on the 100uA range.
Resolution:	This issue has been corrected.

KNOWN ISSUES

Reference number:	AR62218, NS-1241
Symptom:	Rapidly changing the Quickset performance slider between medium and fast settings can result in the slider becoming unresponsive.
Workaround:	Switch to another screen and back to Quickset.

ENHANCEMENTS

Category	Reading buffers <ul style="list-style-type: none"> • Reading buffer memory management now allows users to easily allocate the largest size available when creating a reading buffer. • Additional options are now available when saving data to a USB flash drive. • Buffer statistics and options for accessing data from reading buffers have been added. • Added reading buffer math and unit support. • Added formatting options for writable buffers. • Added a method to clear the active buffer by pressing the MENU + EXIT keys. • When selecting the active buffer, an option now exists to create a new user buffer. • Added the <code>display.activebuffer</code> command and <code>DISPlay:BUFFer:ACTive</code> SCPI command to specify the active buffer for the instrument using remote commands.
Category	Configuration lists <ul style="list-style-type: none"> • Enhanced user interface screen for accessing configuration list settings. • Added the ability to use remote commands to store inactive source and measure function settings in a configuration list index. • Added the ability to use remote commands to query or configure inactive source and measure function attributes.
Category	Trigger model <ul style="list-style-type: none"> • The Measure and Digitize trigger blocks have been combined into a single Measure and Digitize block. The new trigger block either measures or digitizes based on the active function. When used with a Measure Configuration list, this trigger block lets you make sequential measurements with the analog-to-digital converter and the digitizer (when available) in the same trigger model. <ul style="list-style-type: none"> • The SCPI command is <code>:TRIGger:BLOCK:MDIGitize</code>. The TSP command is <code>trigger.BLOCK_MEASURE_DIGITIZE</code>. Digitized measurements are not a feature on the 2450. • The remote commands for the original Measure and Digitize trigger blocks are still accepted to provide compatibility with existing test programs and scripts. However, the trigger models generated with the original commands automatically use the new, combined Measure and Digitize block.
Category	LXI <ul style="list-style-type: none"> • The instrument is now compliant with LXI version 1.5. • An LXI/LAN ID indicator has been added to the System Communications screen. • To discover the instrument, use the LXI Discovery Tool.
Category	Apps <ul style="list-style-type: none"> • When applications are available, the APPS Manager screen displays the apps for the instrument.

<p>Category</p>	<p>New commands and options</p> <ul style="list-style-type: none"> • Added an interlock on and off setting to the user interface and remote commands, <code>:OUTPut[1]:INTerlock:STATe (SCPI)</code> and <code>smu.interlock.enable (TSP)</code>. When enabled, the SMU will not allow the output to be turned on when the interlock is not engaged. • The interlock base behavior has also changed. The SMU output will turn off whenever the interlock is engaged or disengaged. • Added an autorange rebound setting to the user interface and the remote commands <code>[:SENSe[1]] :<function>:RANGe:AUTO:REBound (SCPI)</code> and <code>smu.measure.autorangerebound (TSP)</code>. If autorange rebound is enabled, then after an autoranged measurement, the measure range is restored to match the limit range. • Added a method to automatically install any scripts to internal storage memory that reside in an autoinstall directory on the USB drive when inserted into the instrument. • Added <code>fs.*</code> TSP commands for accessing and managing file system settings. • Added an option to show a Processing screen in the user interface to increase test execution speeds when screen updates are not required. • Added remote commands to set continuous measurement.
<p>Category</p>	<p>Ease of use</p> <ul style="list-style-type: none"> • Numerical entries on the user interface now support Minimum, Maximum, and Infinite options when applicable to the setting. • Option to display the virtual front panel in low resolution to improve communication speed with the instrument. The default screen display resolution of 800 x 480 is reduced to 400 x 240 resolution. • Graph and Histogram settings are now shared for ease of viewing data between the two screens. Also added other graphing enhancements.
<p>Category</p>	<p>General changes</p> <ul style="list-style-type: none"> • The maximum TSP node ID is now 63. The previous maximum was 64. • The Access Mode option on the front panel has been changed to Interface Access. • The user swipe screen is only displayed if user text is defined. • The home screen indication of source limiting has been enhanced to show whether the source limit setting or the measure range is limiting the instrument output.

VERSION V1.6.8B RELEASE

OVERVIEW

The Version 1.6.8b release was not released to the general public. Version 1.6.8b is a minor release that provides one enhancement and one noncritical fix to the function of the safety interlock control.

ENHANCEMENT

AR62555 **Models affected:**
NS1470 All 2450 models, 2460 models, 2461 models

Enhancement:

A new command has been added to control the output when the interlock is not engaged. When enabled, the SMU will not allow the output to be turned on when the interlock is not engaged.

This setting is not affected by a power cycle or a reset.

New TSP command:

The attribute is set to a Boolean value (`smu.ON` or `smu.OFF` or 1 or 0).

```
smu.interlock.enable
```

New SCPI command:

```
:OUTPut[1]:INTerlock:STATe <b>  
:OUTPut[1]:INTerlock:STATe?
```

NONCRITICAL FIX

AR62555 **Models affected:**
NS1470 All 2450 models, 2460 models, 2461 models

Symptom:

If the output is on when the interlock is engaged there may be transient voltages on the output.

Resolution:

The instrument will turn the output off when the interlock is engaged or disengaged.

Version v1.6.7c Release

Overview

Version 1.6.7c is an audited minor release which fixes several different bugs all listed below.

[RELEASED 12-NOV-2018](#)

Critical Fixes

PR61513 Better timer accuracy for times greater than 65 ms.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Using a constant delay block in a TriggerFlow™ takes slightly more time than specified when the delay is greater than 65.5 ms.

Resolution:

The delay time before the extra time is seen has been increased to 1.024 seconds.

PR61508 Restore SmartScale™ button on graph screen after pan/zoom.

AR60539

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Steps to reproduce:

1. View the graph screen.
2. Pan or zoom the graph.
3. The SmartScale button no longer appears.

Resolution:

This issue has been corrected.

NIHK6042 Trigger models hangs with fast NPLC setting.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Setting up a TriggerFlow™ model using the TSP-Link™ trigger lines for synchronization with a fast measurement in a loop can hang waiting for the trigger.

Resolution:

This issue has been corrected.

NIHK4274 TSP-Link performance improvements.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

TSP-Link connection can generate errors if the unit is performing high sample rate or low NPLC measurements.

Resolution:

This issue has been corrected.

NIHK6106 TSP-Link initialization memory leak.

NIHK6239

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Performing a `tsplink.initialize()` command would reduce the amount of available memory slightly each time it executed. This occurred because the firmware was not correctly clearing the group leaders which led to extra memory allocation. Eventually this problem can result in an out of memory condition.

Resolution:

This issue has been corrected.

NIHK6320 TSP-Link node number 64 is no longer selectable.

NIHK6306

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Using TSP-Link node number 64 could cause compatibility issues with older TSP-Link products.

Resolution:

The maximum TSP-Link node number has been limited to 63.

SYS42 Creating a script on a remote TSP-Link node causes a “Node inaccessible” error.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Steps to reproduce:

1. Use `tsplink.initialize()` to create the TSP-Link network.
2. Send the script source to the remote node via the dataqueue
`node[remoteNode].dataqueue.add(myScript.source)`
3. Create the script on the remote node
`node[remoteNode].execute(myScript.name ..
"= script.new(dataqueue.next(), [{" .. myScript.name .."}]))"`
4. The remote node becomes unresponsive and a node inaccessible error is generated.

Resolution:

This issue has been corrected.

SYS535 Using a 2600S, 2600AS, 2600BS, 3706, or a 3706A product as the TSP-Link master results in errors for some commands.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Using a 2600S, 2600AS, 2600BS, 3706, or a 3706A product as the TSP-Link master will generate errors when attempting to use functions or attributes that accept enumeration types.

Resolution:

This issue has been corrected.

NS1131 Sending data to TCP/IP socket is too slow.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

The TCP/IP socket interface can experience long delays before the acknowledge packet is sent from the instrument for large data packets.

Resolution:

This issue has been corrected.

NS1115 Trigger timer does not generate the event at the correct time for long delay settings.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Steps to reproduce:

```
trigger.timer[1].reset()  
trigger.timer[1].delay = delay_time  
trigger.timer[1].start.generate = trigger.ON
```

The event should be generated immediately but will not be generated if `delay_time` is greater than 65.5 ms.

Resolution:

This issue has been corrected.

PR61512 Limit level set incorrectly on function change.
AR60483

Models affected:

All 2450 models, 2460 models

Symptom:

The source limit level could be set incorrectly after changing measure function. This can lead to unexpected source limit conditions, depending on the load and other settings

Resolution:

This issue has been corrected.

NS284 Source range limit checking should generate error on invalid value.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Setting the source range to a value greater than the maximum value would select the highest range but would not generate an error. For 2450 models, the voltage range maximum value is 210 V and for current it is 1.05 A.

Resolution:

This issue has been corrected.

NS967 Output is still ON after turning it OFF and output light is off.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Under certain conditions, creating a configuration list with the output OFF and then recalling it during the execution of a TriggerFlow can result in the output state showing as OFF even when the output is still ON.

Steps to reproduce:

```
reset()
smu.measure.func = smu.FUNC_DC_CURRENT
smu.measure.configlist.create('mList')
smu.source.configlist.create('sList')
smu.measure.configlist.store('mList')
smu.source.configlist.store('sList')
smu.source.func = smu.FUNC_DC_CURRENT
smu.source.output = smu.ON
trigger.model.load('ConfigList', 'mList', 'sList', 0.1)
trigger.model.initiate()
waitcomplete()
smu.measure.func = smu.FUNC_RESISTANCE
print("Expect OFF, found: "..smu.source.output)
smu.source.output = smu.OFF
print("Expect OFF, found: "..smu.source.output)
```

Resolution:

This issue has been corrected.

VERSION V1.6.4C RELEASE

Overview

Version 1.6.4c is an audited minor release which fixes a number of different bugs all listed below.

[RELEASED 23-JUN-2017](#)

Critical Fixes

AR55151 Problem with Abort on Limit. When sweeping voltage, the unit stops prematurely and never reaches the current limit.

AR55431

AR55767

PR61306

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

This bug was introduced with firmware revision v1.6.1a and is fixed with firmware revision v1.6.4c.

Resolution:

This issue has been corrected.

AR55671 Problem with Abort on Limit. Fail warning message 2733 "TM path #1 block #12 ended due to source limit exceeded" is displayed even though the true source limit was not reached.

PR61306

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

This bug was introduced with firmware revision v1.6.3d and is fixed with firmware revision v1.6.4c.

Resolution:

This issue has been corrected.

VERSION V1.6.3D RELEASE

Overview

Version 1.6.3d is an audited minor release which fixes a number of different bugs all listed below.
[RELEASED 18-APR-2017](#)

Critical Fixes

AR54361 2450 Measure Configuration Lists do not save Auto Range setting.
PR60339

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

The Auto Range attribute was not being saved correctly when Config Lists were created. Auto Range was always set to "Off".

Resolution:

This issue has been corrected.

AR54920 Trigger timer does not work correctly for counts > 65535
AR60477

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

Before this enhancement, the TTI products had a limit of 65,535 points for the trigger timer. This limit has been increased to 1,048,575 to match how the 26xx products behave. The trigger timer will now work up to 1,048,575 points.

Resolution:

This enhancement has been made.

PR60362 Output button cannot turn off the output without a power cycle.

Models affected:

All 2450 models, 2460 models, 2461 models

Symptom:

Under certain conditions, when in Ohm Meter mode and changing source values, the instrument will display +0.00000GV or !DispNAN!V and the output button cannot turn off the output without a power cycle.

Resolution:

This issue has been corrected.

PR60377 ENHANCEMENT: Add firmware version and program counter to blue screen information.

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

Whenever a rare system crash occurs and displays a blue screen, valuable information such as firmware revision and program counter (PC) will be displayed to help pinpoint the exact location of the crash.

Resolution:

This enhancement has been made.

PR60504 Trigger model based upon trigger timer sometimes hangs during a long-term test

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

Under certain conditions, creating a trigger model based upon the trigger timer will hang right in the middle of a test that runs for many minutes or longer. This bug was introduced in firmware revision 1.5.0.

Resolution:

This issue has been corrected.

VERSION V1.6.1A RELEASE

Overview

Version 1.6.1a is a Hot Fix against Service Pack 6 firmware v1.6.0i. Only one critical fix was made and no other changes were introduced.

[RELEASED 25-JUL-2016](#)

Critical Fixes

PR59438 HF1: Cannot graph digitizer with track group

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

When customers enable track groups on the graph, data is either wrong or completely missing. This is especially problematic for graphing digitized data and for Demo mode.

Resolution:

This issue has been corrected.

VERSION V1.6.0I RELEASE

Overview

Version 1.6.0i is the sixth official firmware upgrade release for the Model 2450. Known Issues, Usage Notes, and Upcoming Enhancements are listed below in this document.

[RELEASED 18-JUL-2016](#)

Compatibility concerns

n/a

Critical Fixes

PR57048 Instrument not reliably responding to NI VISA “go to local” function
PR57905
AR50675 **Models affected:**

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

Under certain conditions customers are not able to reconnect to the 2450 after remote operation and manually placing the 2450 into local mode.

Resolution:

This issue has been corrected. The instrument will now go into “local mode” after issuing the “logout” command.

PR58210 Buffer file contains extra NULL values.
AR52304 **Models affected:**

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

When saving a databuffer on the DMM7510 form the internal webpage the databuffer will insert NULL values into the CSV file. When saving a buffer from the front panel of the instrument there are no NULL values inserted for the same data set.

Resolution:

This issue has been corrected. Extra NULL characters are no longer generated.

PR58329 There are complaints about swipe screen performance.
AR52702 **Models affected:**

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

Most swipe screens appear to move more slowly than in previous firmware revisions.

Resolution:

This issue has been corrected. Swipe screen action has been restored to previous versions of firmware and has been slightly sped up.

PR58384 Downgrading from firmware revision v1.5.0 to v1.3.0 will cause the unit to reboot unnecessarily.
AR52713

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

When downgrading firmware from v1.5.0 to v1.3.0, a warning message window instructing the user to remove existing scripts will display and then the unit will reboot unconditionally.

Resolution:

This issue has been corrected in version v1.6.0 and later. The unit will only reboot if the user proceeds with the downgrade.

PR58469 Pressing the <HOME> button 2 times behavior changes from v1.3.0 to v1.5.0.
AR52717

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

Feature definition on FW 1.3.0s or earlier is push HOME key once goes to last swipe screen on the home screen. Pushing HOME key a 2nd time takes you back to home swipe on the home screen. FW1.5.0g does not do that 2nd HOME key action.

Resolution:

This issue has been corrected. Previous behavior has been restored.

PR58719 The trigger model locks up when using a Delay List.
AR52324

Models affected:

All 2450 models

Symptom:

Under certain conditions, when programming one of the timers to use a delay list, the trigger model task 'locks up'. The only remedy is to abort operation and reset the instrument.

Resolution:

This issue has been corrected.

PR51021 TSP-Link: Inactive nodes are not removed after the next tsplink reset().

Models affected:

All 2450 models

Symptom:

The 26xxA/B correctly removes index in the "node" table that are no longer present. On the 2450, a second tsplink reset() does not remove a tsplink node that had its address changed or was reconfigured from the node table after a tsplink reset().

Resolution:

This issue has been corrected.

PR56486 Calling `tsplink.initialize()` under specific conditions can cause slave to lockup.

Models affected:

All 2450 models

Symptom:

Under certain conditions, when connecting 2 or more 2450s, certain scripts will cause the Master SMU to no longer respond over the bus or from the front panel.

Resolution:

This issue has been corrected.

PR56487 Calling `tsplink.initialize()` under specific conditions can cause slave to lockup.

Models affected:

All 2450 models

Symptom:

Attempting to initialize TSP-Link using `tsplink.initialize()` may result in the following error being reported:

```
TSP-Error 1202: Link initialization failed
```

One or more of the slave instruments may lockup.

Resolution:

This issue has been corrected.

PR56812 TTI Instruments do not work well when TSP-Linked to a Model 26xx.

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

When hooking up (4) 26xx-X SMUs to each other in series (one of which is the master) and then putting a TTI Instrument on the end, the box will lock up after the 3rd `tsplink.reset()`. The problem gets worse if you start hooking instruments in parallel.

Resolution:

This issue has been corrected.

PR57761 TSP-Link node at address 64 error when using "enum" eg. trigger.EVENT_DISPLAY.

Models affected:

All 2450 models

Symptom:

TSP-Link enum sharing was not properly accounting for 1-based node numbers when generating bit masks. Therefore, node 64 would get completely shifted away and become zero.

Resolution:

This issue has been corrected.

PR58964 Timing problem with Autoexec scripts.

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

Certain scripts that have been designated as 'default' or Autoexec scripts will start running before the system has completely booted up. This may cause the Autoexec script to get skipped and not executed at all upon first boot up.

Resolution:

This issue has been corrected.

Enhancements

PR56495 **Models affected:**

All 2450 models, 2460 models, 2461 models, 7510 models

Enhancement:

When turning on REL, the units on the graph should not change. This behavior has been implemented.

PR58734 **Models affected:**

All 2450 models, 2460 models, 2461 models, 7510 models

Enhancement:

The reading tables have been enhanced to visually differentiate between OVERFLOW and LIMITS. Overflow readings will now be set to **RED TEXT** and Limits will be set to **YELLOW TEXT**.

Noncritical Fixes

PR58864 Swipe screen content disappears after pressing the home key on large reading screen.

Models affected:

All 2450 models, 2460 models, 2461 models, 7510 models

Symptom:

Under certain sequences of events, after minimizing the default swipe screen and then pressing the HOME button, certain content on the swipe screen will be missing.

Resolution:

This issue has been corrected.

Known issues

n/a

VERSION V1.5.0G RELEASE

Overview

Version 1.5.0g is the fifth official firmware upgrade release for the Model 2450. Known Issues, Usage Notes, and Upcoming Enhancements are listed below in this document.

[RELEASED 11-MAR-2016](#)

Compatibility concerns

Firmware revision v1.5.0g can be installed on any vintage 2450. After upgrading to v1.5.0g, be advised that in order to downgrade back to previous versions of firmware, you **MUST** archive and remove all saved scripts before the downgrade will be allowed.

Critical Fixes

PR56630 Problem with Trigger Model not waiting.

AR50775

Models affected:

All 2450 models

Symptom:

Under certain conditions when an SMU is connected to a digitizing instrument (2461 or DMM7510) the digitizer will start digitizing before the trigger has been sent to start it.

Resolution:

This issue has been corrected.

PR57147 Generating Sweep parameters does not save correctly in the Config List.

AR51367

Models affected:

All 2450 models

Symptom:

When creating a new Source Config List and then immediately saving this Config List to a script, the instrument will hang.

Resolution:

This issue has been corrected.

PR57991 Hardware is in the wrong state at boot up.

AR52304

Models affected:

All 2450 models

Symptom:

From initial boot-up and factory default settings, if you have the 2450 force 1 volt into 1G Ω , we expect 1nA of current. But instead 2450 reports only 0.100 nA. If one configures the instrument to force current (1nA) and measure voltage, the expected 1 volt is measured. Thereafter, returning to force 1V and measure current will yield the expected 1nA value. This issue can be observed from both the front and rear terminals.

Resolution: This issue has been corrected. The 2450 now boots up into the exact desired state.

PR56931 Throw an error is auto-range low is set and the source and measure function match.

Models affected:

All 2450 models

Symptom:

Certain command sequences will cause the SMU to display an error and this error is not consistent between the 2450, 2460, and 2461.

Resolution:

This issue has been corrected and the error message between the 2450, 2460, and 2461 now match.

PR56942 Sort binning template's constant limit blocks are jumping to the wrong blocks.

Models affected:

All 2450 models

Symptom:

When the SortBinning template was originally ported to the 2450, it correctly moved the notify block for external output. However, it did not correctly renumber the constant limit block's branch to block value.

Resolution:

This issue has been corrected.

PR56964 Virtual front panel scrolling issue.

Models affected:

All 2450 models

Symptom:

When using the virtual front panel, the user is unable to scroll up and down in the system settings menu. Using the web interface, the user should be allowed to at least scroll through the system settings.

Resolution:

This issue has been corrected.

PR57014 Memory corruption when using a Config List over 60,000 indexes.

Models affected:

All 2450 models

Symptom:

When creating a Config List of greater than 60,000 indexes, when trying to retrieve values above index 60,000, the wrong index was retrieved and the number of indexes over-flowed.

Resolution:

This issue has been corrected. The maximum number of indexes is correctly supported up to 1,000,000.

PR57059 Limit is wrongly reported after a range change.

Models affected:

All 2450 models

Symptom:

Under certain conditions, the Limit indicator is on in error. This was likely to occur when sourcing voltages at or very close to the source limit and sourcing into an OPEN and changing the measure range to a higher range.

Resolution:

This issue has been corrected.

PR57207 Incorrect source value after using OCOMP ohms.

Models affected:

All 2450 models

Symptom:

Under certain conditions, after running OCOMP ohms and immediately switching ranges while digitizing, an incorrect source value is returned.

Resolution:

This issue has been corrected.

PR57265 Certain scripts cause error code 5093 "Cannot change the source function, range, level, or limit when using the Resistance measure function."

Models affected:

All 2450 models

Symptom:

Certain scripts cause the "createconfigscript()" function to put a source function call after the measure resistance function.

Resolution:

This issue has been corrected.

PR57512 Cursor statistics don't display if $x1 > x2$.

Models affected:

All 2450 models

Symptom:

Notice that the stats are displayed as long as $x2$ is to the right of $x1$. As soon as they cross, hash marks are displayed for all stats.

Resolution:

This issue has been corrected.

Enhancements

No PR **Models affected:**

All 2450 models

Enhancement:

The behavior of the command `display.waitevent()` has changed. When the example below is run, a dialog will be shown. If Yes or No is not pressed within 1 second, then `display.waitevent()` will time out. The `buttonId` will now contain `display.BUTTON_SELF` instead of 0 (zero). It will also return `display.BUTTON_SELF` if the prompt is removed with `display.delete()`.

```
display.prompt(display.BUTTONS_YESNO, "Press Yes or No...")
objectID, buttonId = display.waitevent(1)
```

PR57905 **Models affected:**

AR50675

All 2450 models

Enhancement:

Add a command to put the instrument into LOCAL mode.

The command `logout` can be used to log out of remote mode and force the instrument into LOCAL mode. This command was previously failing in certain situations. This command is now fully supported.

Noncritical Fixes

n/a

Known issues

n/a

VERSION V1.3.0S RELEASE

Overview

Version 1.3.0s is the fourth official firmware upgrade release for the Model 2450. Known Issues, Usage Notes, and Upcoming Enhancements are listed below in this document.

[RELEASED 10-JUN-2015](#)

Compatibility concerns

Firmware revision v1.3.0s can be installed on any vintage 2450.

Active Buffer Behavior Starting with v1.3.0s, the behavior of the Active Buffer has changed. Prior to v1.3.0s, the Active Buffer was always `defbuffer1` by default. Now with v1.3.0s, the Active Buffer will be the most recently created or selected buffer. Additionally, while graphing data, when a user creates or selects a new buffer, that data will automatically be graphed. This feature can be disabled by manually selecting another trace and deleting (if desired) the active trace. The user can also just select a different buffer.

Critical Fixes

PR50999 AR39793 Need better indication when unit is in continuous trigger mode when set to 10PLC and 100 count repeat filter

Models affected:

All 2450 models

Symptom:

During some types of measurements the 2450 will appear to be stuck with no activity. The solution is to add an animated indicator to show that measurements are still taking place and the 2450 is active.

Resolution:

This issue has been corrected. There is now an active indicator for continuous readings, even when the reading will be coming in very slowly, the indicator displays that the test is still running.

PR51112 AR39909 USBTMC: Error returned every other time status byte requested via USB

Models affected:

All 2450 models

Symptom:

This issue was discovered after writing a Status Byte routine in LabVIEW™ which enables the user to query the status byte in a loop. Every other time STB was requested, an error was returned.

Resolution:

This issue has been corrected.

PR51359 Resistor Sorting Trigger Model Example Incorrect
AR40280

Models affected:

All 2450 models

Symptom:

The examples which are explained on page 3-78 in 2450 Reference Manual (2450-901-01 Rev. B / September 2013) are wrong.

Resolution:

This issue has been corrected. All diagrams and coding examples have been updated and verified.

PR51544 Y-Axis units on the graph do not update properly when changing functions
AR40577

Models affected:

All 2450 models

Symptom:

When graphing measurements as a function of time, and then you change functions (say from resistance to current), the units do not update properly on the Y-axis unless you go to one of the tabs on screen and then go back to the Graph or if the unit auto scales.

Resolution:

This issue has been corrected.

PR51545 Unit intermittently hangs up when pressing the HOME key from the Graph Page
AR40578

Models affected:

All 2450 models

Symptom:

Intermittently when on the Graph page and then pressing the HOME key, the unit will hang up and must be rebooted.

Resolution:

This issue has been corrected.

PR55123 Autoexec script cannot be aborted
AR42424

Models affected:

All 2450 models

Symptom:

If there is a problem with any script that has been set to run automatically at power up (autoexec), it cannot be aborted.

Resolution:

This issue has been corrected.

PR55188 :READ? Query always returns the last reading at the end of the continuous buffer.
AR42592

Models affected:

All 2450 models

Symptom:

For example, if a basic measurement is set up to defbuffer1 (size 10000) and then takes 11000 readings, the last 1000 readings will all return the same value. This should act as a circular buffer.

Resolution:

This issue has been corrected.

PR55281 Problem with certain trigger block configurations
AR42407

Models affected:

All 2450 models

Symptom:

If setting several Notify Blocks with Line#1 as PASS signal trigger, Line#2 as FAIL signal trigger, and Line#4 as EOT signal trigger, for example, in the TriggerFlow, you will find any single Notify Block with Line#X would give out trigger out signals on Line#1,#2,#4 in the same time.

Resolution:

This issue has been corrected.

PR55600 *TRG command trigger source does not work in SCPI mode trigger model.

Models affected:

All 2450 models

Symptom:

Using a trigger model .wait block with the command event in SCPI does not work when *TRG is sent. Instead, it generates the following error ==> Error 2713 - "No trigger model engine available".

Resolution:

This issue has been resolved. Now, the *TRG command will satisfy the wait block when sent if waiting for a command event.

PR55867 1uA Current Source error when using Config List
AR43082

Models affected:

All 2450 models

Symptom:

Under a very specific sequence of events, setting the Source Config List source value to 1.0uA will revert to 0uA after pressing the Trigger button on the front panel.

Resolution:

This issue has been corrected.

PR56135 QuickSet Performance Setting does not work on fastest setting
AR50078

Models affected:

All 2450 models

Symptom:

On the QuickSet Menu, when editing the Performance Slide bar, if you choose the fastest speed, the dial indicates a speed of ~1700/sec. However, the actual speed is only 10/sec no matter how much the other settings are optimized. The only way to achieve this speed is to create a simple trigger model configuration that sources, measures, and loops back continuously, then manually set NPLC to .01, turn auto ranging for source and measure off, and set source delay to 0.

Resolution:

This issue has been corrected and the Performance Slide bar works correctly for all settings.

Enhancements


GENERAL Models affected:

All 2450 models

Enhancement:

A number of improvements have been made to the overall Graphical User Interface as follows:

1. Screen Colors: All screen colors have been modified for better contrast and easier readability.
2. Pinch-to-Zoom Performance: Throughout the user interface, the “Pinch-to-zoom” touch screen motion has been improved and is more responsive.
3. Improve Swiping:
 - a. The swipe user interface gesturing has been dramatically improved and is more responsive.
 - b. Added Vertical Swiping in various screens in the GUI.
 - c. Horizontal swiping has been made more smooth and is consistent with Vertical Swiping.
 - d. “Fling” swiping has been implemented where faster swiping actions result in rapid scrolling followed by decay based on the velocity of the “fling.”
 - e. Swipe Down on the Home screen will display larger readings.
4. Tabs and Buttons: Throughout the user interface multiple data display options have been made available through tabs (header bars) with swipe screen indicators to show how many options are available and which display tab is active.




5. Graphing:
 - a. New Auto Scale Options (X-Axis) → Track Latest, Track Group
 - b. New Auto Scale Options (Y-Axis) → y-swim lanes, y-shared, y-per trace
 - c. Multi-Trace Line Plots
 - d. Multi-Trace Scatter Plots
 - e. Various refresh and performance improvements

6. Histogram:
 - a. New Auto-Scale, Auto-Bin, and Fit
 - b. Smartscale choose best scaling option
 - c. Various refresh and performance improvements

7. TTI Synchronization: All Touch, Test, Invent™ Keithley Models including the 2450, 2460, and 7510 have been carefully updated so that they are all consistent in look, feel, and general navigation.

8. Updated Reading Table: Added new reading table features and a new Reading Preview Graph. Please see the Reference Manual for further details.

READING TABLE			
Buffer	Active (defbuffer1) 		
Buffer Index	Time	Reading	Source
78824	06/10 07:16:22.174568	+0.009484 μ A	+001.9090 mV
78825	06/10 07:16:22.845109	+0.009590 μ A	+001.9310 mV
78826	06/10 07:16:23.515734	+0.009564 μ A	+001.9228 mV
78827	06/10 07:16:24.186322	+0.009647 μ A	+001.9427 mV
78828	06/10 07:16:24.856892	+0.009639 μ A	+001.9420 mV
78829	06/10 07:16:25.527470	+0.009541 μ A	+001.9195 mV
78830	06/10 07:16:26.198087	+0.009517 μ A	+001.9151 mV
78831	06/10 07:16:26.868617	+0.009631 μ A	+001.9391 mV
78832	06/10 07:16:27.539214	+0.009617 μ A	+001.9381 mV
78833	06/10 07:16:28.209799	+0.009630 μ A	+001.9398 mV

PR50885 **Models affected:**
 AR39690 All 2450 models

Enhancement:

Add a direct shortcut from the HOME view measurement line to the measurement settings menu.

A shortcut icon has been added to the swipe bar on the HOME source/measurement tab.



PR51356 **Models affected:**
AR40325

All 2450 models

Enhancement:

Add a CLEAR or ENTER parameter to the WAIT block of the trigger model.

The CLEAR or ENTER or NEVER was added the WAIT block on the trigger screen.

PR53815 **Models affected:**

All 2450 models

Enhancement:

Add a :TRIGger:LOAD command that takes a template name as a first argument

Old Command

```
:TRIGger:LOAD:EMPTY
:TRIGger:LOAD:CONFiguration:LIST
:TRIGger:LOAD:TRIGger:EXternal
:TRIGger:LOAD:LOOP:SIMple
:TRIGger:LOAD:LOOP:DURation
<not present>
<not present>
<not present>
```

New Command

```
:TRIGger:LOAD "Empty"
:TRIGger:LOAD "ConfigList", <parameter list as before>
:TRIGger:LOAD "LogicTrigger", <parameter list as before>
:TRIGger:LOAD "SimpleLoop", <parameter list as before>
:TRIGger:LOAD "DurationLoop", <parameter list as before>
:TRIGger:LOAD "LoopUntilEvent", <parameter list as before>
:TRIGger:LOAD "GradeBinning", <parameter list as before>
:TRIGger:LOAD "SortBinning", <parameter list as before>
```

Example:

before:

```
:TRIGger:LOAD:LOOP:DURation <duration>, <delay>, "<reading buffer>"
```

after:

```
:TRIGger:LOAD <duration>. <delay>, "<readingBuffer>"
```

Usage Notes:

- The template name is not case-sensitive
- The template name needs to be in quotes
- This makes the SCPI command more like the TSP equivalent trigger.model.load() command
- See the Reference Manual for more details

PR55190 **Models affected:**
AR42567

All 2450 models

Enhancement:

Change the Voltmeter default source range from 10uA to 10mA.

In order to speed things up, and to better measure voltages on more inductive loads, the default source range for the Voltmeter QuickSet has been changed from 10uA to 10mA.

PR56127 Models affected:

All 2450 models

Enhancement:

Add an API command to mark the start of a group for writable buffers.

A status optional parameter has been added to the following TSP and SCPI commands:

SCPI

```
TRACe:WRITe:READIng <standard writable reading buffer>, <reading value>,  
[<time sec>, <time nsec>, [<status>]]
```

```
TRACe:WRITe:READIng <full writable reading buffer>, <reading value>,  
<extra value>, [<time sec>, <time nsec>, [<status>]]
```

TSP

```
buffer.write.reading(<standard writable reading buffer>, <reading value>,  
[<time sec>, <time nsec>], [<status>])
```

```
buffer.write.reading(<full writable reading buffer>, <reading value>,  
<extra value>, [<time sec>, <time nsec>], [<status>])
```

The optional status parameter indicates if the reading being added is start of group for plotting on the graph. The default is 0. Set this to 0 if not start of group or set to 256 if start of group. This parameter only accepts 0 or 256 - any other value generates an error. For TSP, `buffer.STAT_START_GROUP` can be used to set it. You would set status to 256 to help graph a family of curve traces on the graph.

Noncritical Fixes

PR50249 **Models affected:**

All 2450 models

Symptom:

GPIB: The SRQ annunciator does not get lit for GPIB, works ok for USB and VXI-11.

Resolution:

This issue has been corrected.

PR50426 **Models affected:**

All 2450 models

Symptom:

Clearing Limit 2 will clear the Limit 1 annunciator on the display instead of the Limit 2 annunciator.

Resolution:

This issue has been corrected.

Known issues

N/A

VERSION V1.2.0F RELEASE

Overview

Version 1.2.0f is the third official firmware upgrade release for the Model 2450. Known Issues, Usage Notes, and Upcoming Enhancements are listed below in this document.

[RELEASED 7-JAN-2015](#)

Compatibility concerns

Firmware revision v1.2.0f can be installed on any vintage 2450.

Critical Fixes

AR40324 **Models affected:**

PR51382 All 2450 models

Symptom:

The limit values in trigger.BLOCK_BRANCH_LIMIT_CONSTANT are saved incorrectly in the Create Config operation.

Under certain conditions, limit values are saved as zero.

Resolution:

This issue has been corrected.

AR40457 **Models affected:**

PR51440 All 2450 models, SCPI2400 mode only
PR51987

Symptom:

Source Memory Sweep does not work properly when Source Auto Clear is enabled.

Resolution:

This issue has been corrected.

AR40488 **Models affected:**

AR40573 All 2450 models
AR40575
PR51449

Symptom:

Calibration date is set to 03/16/1996 after updating from v1.0.0i to v1.1.0s. This is due to the fact that a new field was added between v1.0.0i and v1.1.0s and the new field was not initialized properly.

Resolution:

This issue has been corrected and Calibration Date will be set to the old Calibration Adjust Date if not already initialized.

AR40579 Models affected:

PR51546 All 2450 models

Symptom:

Black bars appear across the bottom of the screen capture image.

Resolution:

This issue has been corrected.

AR40591 Models affected:

PR51537 All 2450 models

Symptom:

When capturing multiple screen shots in succession, the following error would sometimes occur.

```
2350 Internal: SPLAT! drop packet to input queue
```

Resolution:

This issue has been corrected.

AR41514 Models affected:

PR52399 All 2450 models

Symptom:

VISA Device Clear over USB sometimes causes timeout and data loss.

Resolution:

This issue has been corrected.

AR41552 Models affected:

PR52941 All 2450 models

Symptom:

Under certain test setups, *RST (and front panel reset) will cause voltage spike at the output.

Resolution:

Voltage spikes after *RST (and front panel reset) have been greatly reduced.

AR41757 **Models affected:**
PR53544
PR54481 All 2450 models

Symptom:

When sourcing current on the 100mA range or lower, and the instrument ranges up to the 1A range, the source value may be incorrectly rounded.

Resolution:

This issue has been corrected.

AR42086 **Models affected:**
PR54659 All 2450 models

Symptom:

When source read-back is turned off, the programmed source values are returned. If the programmed values are less than 1 volt, the returned values are incorrect due to rounding problems.

Resolution:

This issue has been corrected.

Enhancements

PR48621 **Models affected:**
All 2450 models

Enhancement:

Implement and document procedure for Clearing Memory and Data Sterilization for the Model 2450. This document can be requested from the Keithley Instruments Quality team.

PR53367 **Models affected:**
All 2450 models

Enhancement:

Add SCPI equivalent for `trigger.LOG_WARN_ABORT`.

added `ABORT` as the equivalent

```
trig:bloc:log:even 1, abort, "abort message"
```

```
trig:bloc:list?
```

```
LOG_EVENT EVENT: # 2733 MESSAGE: "abort message"
```

Noncritical Fixes

PR50249 Models affected:

All 2450 models

Symptom:

GPIB: The SRQ annunciator does not get lit for GPIB, works ok for USB and VXI-11.

Resolution:

This issue has been corrected.

PR50426 Models affected:

All 2450 models

Symptom:

Clearing Limit 2 will clear the Limit 1 annunciator on the display instead of the Limit 2 annunciator.

Resolution:

This issue has been corrected.

PR51390 Models affected:

All 2450 models

Symptom:

The command

```
value = display.input.prompt(display.BUTTONS_YESNO, "Do you want to  
continue?")
```

will cause the variable "value" to return nil.

Resolution:

This issue has been corrected.

PR51807 Models affected:

All 2450 models

Symptom:

Some measure attributes are not saved in the Measure Configuration List.

smu.measure.configlist.recall() does not restore the following attributes:

- Display digits
- Limit auto clear
- Math percent
- User delay (1 through 5)

If the filter is not enabled, the following attributes are not restored:

- Filter count
- Filter type

If relative offset is not enabled, the following attribute is not restored:

- Relative offset value

Resolution:

This issue has been corrected.

PR54651 **Models affected:**

All 2450 models

Symptom:

Changing the measure range low setting (used for auto-range) could result in incorrect operation if the range is higher than the active measure range.

Resolution:

This issue has been corrected.

Known issues

N/A

VERSION V1.1.0S RELEASE

Overview

Version 1.1.0s is the second official firmware upgrade release for the Model 2450. Known Issues, Usage Notes, and Upcoming Enhancements are listed below in this document.

[RELEASED 14-FEB-2014](#)

Compatibility concerns

This version of firmware cannot be installed on newer 2450 systems. Also, once any system is updated to firmware revision v1.2.0f or later, firmware version v1.0.0s can NEVER be installed again.

Critical Fixes

PR50333 **Models affected:**
AR39747 All 2450 models

Symptom:

2450 should not measure resistance with output off.
Because resistance measurements are dependent on the current or voltage source, resistance measurements with the source off are meaningless and will be confusing to the user.

Resolution:

This issue has been corrected. Once the output has been turned on/off once, the 2450 will display UNAVL (unavailable) in the upper right corner and the measurement fields will display dashes.

PR50703 **Models affected:**
AR39206 All 2450 models

Symptom:

The graph shows voltage drop as current instead of current when sourcing current and then selecting source as the Y-axis.

Resolution:

This issue has been corrected.

PR50704 **Models affected:**
AR39257 All 2450 models

Symptom:

When certain sequences of SCPI commands using the :TRIG:LOAD:LOOP command were sent, the 2450 would throw a Fatal System Error requiring a 2450 power cycle to recover.

Resolution:

This issue has been corrected.

PR50750 **Models affected:**
AR39364 All 2450 models

Symptom:

When setting up a source configuration list, in some cases the source configuration list screen on the front panel GUI will show a source limit value of "None" if a config list point is selected.

Resolution:

This issue has been corrected.

PR50860 **Models affected:**
AR39658 All 2450 models

Symptom:

When zooming in on the graph, the magnitude of the data changes incorrectly. Sometimes the actual graph area of interest will scroll out of sight.

Resolution:

This issue has been corrected. The overall graph zooming capability has been dramatically improved.

PR50998 **Models affected:**
AR39795 All 2450 models

Symptom:

In certain cases, when setting up a Dual Sweep, the last point of the Source Configuration List is incorrect.

Resolution:

This issue has been corrected.

PR51005 **Models affected:**
AR39859 All 2450 models

Symptom:

There was an inconsistency in the *CLS command behavior with SCPI and 2400SCPI modes. In SCPI and 2400SCPI modes, the Output Queue was not always cleared properly. In TSP mode, the command sometimes returned Error Code -410 Query Interrupted or Error Code -420 Query Unterminated.

Resolution:

This issue has been corrected.

PR51046 **Models affected:**
AR39957 All 2450 models

Symptom:

When a Source Configuration List is generated in the TriggerFlow Model, everything works OK. When the Source Configuration List is saved and then recalled, the 2450 sometimes returns the Error Code - 221 Conflict Error because the Current Range of all of the Source Points is always saved to the 100uA range.

Resolution:

This issue has been corrected.

PR51263 **Models affected:**
AR40267 All 2450 models

Symptom:

Sometimes, the Abort on Source Limit setting does not work when the 2450 performs Voltage Sweeping and reaches the Source Limit.

Resolution:

This issue has been corrected.

PR51051 **Models affected:**
AR40159 All 2450 models

Symptom:

Extra Current Steps occur between Current Source Range transitions when using the Source Configuration List.

Resolution:

This issue has been corrected.

PR51186 **Models affected:**
AR39968 All 2450 models

Symptom:

2450 crashes after long period of time running through LabVIEW™.

Resolution:

This issue has been corrected.

Enhancements


PR50774 Models affected:

All 2450 models


Enhancement:

Implement new Virtual Front Panel capability.


To access the new Virtual Front Panel, access the 2450 through Ethernet using your favorite Internet browser.



When asked for a Username and Password: enter the Username and Password for that particular 2450. The default Username is `admin` and the default Password is `admin`.



An example of the 2450 Virtual Front Panel is shown below. Users can use their mouse from a standard PC to control the instrument. Users can also use touch screens from most touch screen devices that can access the 2450 IP address.



PR50906 Models affected:

All 2450 models

Enhancement:

2450 Quick Start Guide, User Manual, and Reference Manuals have all been updated.

The 2450 Release Notes for Firmware Revision v1.1.0s have also been updated and are available at the Keithley Instruments, Inc. website.

PR50231 Models affected:

All 2450 models

Enhancement:

Implement and document procedure for Customer onsite Calibration of Model 2450.

This capability is scheduled to be available late Q1'2014. Please check back at <https://www.tek.com/keithley> for updates in early April 2014.

PR48744 Models affected:

All 2450 models

Enhancement:

Provide capability for customers to save screen capture files from the front panel to the USB Flash Drive.

This capability is documented in Rev-C of the 2450 Reference Manual in Section 2 Page 44 (2-44).

In short, with a valid USB Flash Drive inserted into the front USB port of the 2450, press the <HOME> and <ENTER> keys simultaneously and the current screen image will be saved to the USB Flash Drive.

PR50657 Models affected:

All 2450 models

Enhancement:

The maximum number of characters allowed for naming a Reading Buffer on the front panel GUI was 18 characters. The bus commands allow up to 32 characters. The GUI maximum number of characters has been updated to 32 to match the bus command limit.

PR50662 Models affected:

All 2450 models

Enhancement:

Add a password verification method to the 2450 GUI.

When changing the 2450 system password, the user will be prompted to enter the password a second time. The second entry will be used to verify that the first and second passwords match and that the intended password has indeed been entered. If the two passwords do not match, an error dialog is displayed and the users is instructed to try again.

PR50758 Models affected:

All 2450 models

Enhancement:

Scripts can be written in TSB and downloaded to the model 2450. However, scripts do not enable the user to input values from the front panel. The 26xx family of SMUs allows users to input values into their scripts real time.

Starting with firmware revision v1.1.0s, functionality has been added to the 2450 that allows users to input values into the scripts real-time from the front panel.

The new commands are as follows:

```
display.input.number()
display.input.option()
display.input.prompt()
display.input.string()
```

These commands are documented in Rev-C of the 2450 Reference Manual in Section 8 Page 51 (8-51).

PR50866 Models affected:

All 2450 models

Enhancement:

The 2450 System Information window has been updated to show calibration adjustments vs. calibration without adjustment dates. The System Information window now presents these dates as follows.

Adjust Date	11/19/2013
Adjust Count	1
Calibration Date	4/17/2014

PR50876 Models affected:

All 2450 models

Enhancement:

The behavior of the *LANG? command on the 2450 has been changed as follows.


Sending the query *LANG? over a non-controlling interface will no longer change the interface control of the unit. For example, if the unit is under local control, then sending the *LANG? over Telnet, USB, or GPIB will leave the unit under local control. This was done in order for KickStart (or any other remote control software) to query connected/accessible instruments without resetting them or changing or disturbing the current trigger model.

PR51248 Models affected:

All 2450 models

Enhancement:

The 2450 built-in webpage has been enhanced to show a historical list of commands recently sent to the instrument. This new COMMAND OUTPUT window has been added to the Send Commands section of the webpage.



PR51249 Models affected:

All 2450 models

Enhancement:

The 2450 built-in webpage has been enhanced. A new button “Return Error” has been added to allow users to easily query the last unread error number and error message. This new functionality works in both TSP and SCPI modes.

Noncritical Fixes

PR50285 Models affected:

All 2450 models

Symptom:

On the Manage Scripts window, the Left Arrow and Delete buttons remain enabled and active even after a USB Flash Drive has been removed from the instrument.

Resolution:

This issue has been corrected.

PR50404 Models affected:

All 2450 models

Symptom:

TSP-Link reset or initialization may consistently fail on some 2450 units. The unit being reset may ignore the reset, stop responding to bus commands, and/or display “Slave” in the Communication Status Indicator.

Resolution:

This issue has been corrected.

PR50670 Models affected:

All 2450 models

Symptom:

The LAN Reset button on the back of the 2450 failed to reset the system password.

Resolution:

This issue has been corrected and the system password is reset to the default, **admin**.

PR50772 Models affected:

All 2450 models

Symptom:

Offset Compensation for SVMI (ohms) and Offset Compensation for SIVM (ohms) did not perform the offset measurement correctly.

Resolution:

This issue has been corrected.

PR50785 Models affected:

All 2450 models

Symptom:

On the TriggerFlow Screen, the default Bit Pattern and Bit Mask show 255. Since there are only 6 trigger lines on the 2450, the maximum Bit Pattern should be no more than 63.

Resolution:

This issue has been corrected. The maximum value for Bit Pattern is now 63. The maximum value for Bit Mask remains 255.

PR50786 Models affected:

All 2450 models

Symptom:

Digital I/O Trigger blocks behavior functionality was not correct.

Resolution:

For Digital I/O Trigger blocks, as the mask setting changes, any bits that are set to 1 will have the corresponding Digital I/O line set to Digital I/O Output Mode. For bits set to 0, those corresponding Digital I/O line modes remain unchanged.

PR50899 Models affected:

All 2450 models

Symptom:

The default value for Source Current Range displayed on the front panel does not match the actual Source Current Range value.

Resolution:

The default Current Source Range is now 10nA in (2450) SCPI mode.

PR50903 Models affected:

All 2450 models

Symptom:

Source Current and Source Voltage Levels have incorrect Min and Max Values.

`:SOURce[1]:CURRent[:LEVel][:IMMediate][:AMPLitude]` reports that the minimum acceptable value is -1.00 and maximum is 1.00 when they should be -1.05 and 1.05, respectively.

Resolution:

This issue has been corrected.

PR50979 Models affected:

All 2450 models

Symptom:

If a Sweep Function encounters a Source Limit Value Event, the Source will not turn off.

Resolution:

This issue has been corrected. The 2450 will now automatically turn off the Source Output if a Source Limit Event occurs.

PR51033 Models affected:

All 2450 models

Symptom:

Sending `*IDN?` over USB TMC causes the unit to switch into USBTMC control instead of staying with the current active interface. It also puts the trigger model back into IDLE mode.

Resolution:

This issue has been corrected.

PR51205 Models affected:

All 2450 models

Symptom:

ICL command "display.changescreen()" can lock up after the command "reset()" is called over and over again.

Resolution:

This issue has been corrected.

Known issues

PR48636 Model 2450 does not respect a USB Flash drive file that is read only.

Models affected:

2450

Symptom:

The 2450 will write over read-only files on flash drives. For example, if the 2450 attempts to write to file aaa.txt and aaa.txt is marked read-only, the 2450 will rewrite file aaa.txt without warning. This problem does NOT suggest the 2450 randomly overwrites arbitrary files on a flash drive.

Workaround:

There is no known workaround for this issue at this time.

PR49308 `trigger.BLOCK_BRANCH_COUNTER` loop without a measure or delay block appears to hang.

SCPI: `:TRIGger:BLOCK:BRANch:COUNter`

TSP: `trigger.model.setblock()` with `trigger.BLOCK_BRANCH_COUNTER`

Models affected:

2450

Symptom:

When running a tight trigger loop without a measurement or delay in the sequence, the 2450 will be unresponsive until the loop ends.

Workaround:

Add any measurement or short delay in the trigger loop and the 2450 will perform normally. A future firmware release will work around this problem automatically.

VERSION V1.0.0I RELEASE

Overview

Version 1.0.0i is the initial firmware release for the Model 2450. No fixes are listed since this is the very first firmware release. Known Issues, Usage Notes, and Upcoming Enhancements are listed below in this document. [RELEASED 31-JUL-2013](#)

Compatibility concerns

This version of firmware cannot be installed on newer 2450 systems. Also, once any system is updated to firmware revision v1.2.0f or later, firmware version v1.0.0i can NEVER be installed again.

Critical fixes

N/A

Enhancements

N/A

Noncritical fixes

N/A

Known issues

PR48636 Model 2450 does not respect a USB Flash drive that is read only.

Models affected:

2450

Symptom:

The 2450 will write over read-only files on flash drives. Specifically, if the 2450 attempts to write to file aaa.txt and aaa.txt is marked read-only, the 2450 will rewrite file aaa.txt without warning. This problem does NOT suggest the 2450 randomly overwrites arbitrary files on a flash drive.

Workaround:

There is no known workaround for this issue at this time.

PR49308 `Trigger.BLOCK_BRANCH_COUNTER` loop without a measure or delay block causes hang.

SCPI: `:TRIGger:BLOCK:BRANch:COUNter`

TSP: `trigger.model.setblock()` with `trigger.BLOCK_BRANCH_COUNTER`

Models affected:

2450

Symptom:

When running a tight trigger loop without a measurement or delay in the sequence, the 2450 will be unresponsive until the loop ends.

Workaround:

Simply add any measurement or short delay in the trigger loop and the 2450 will perform normally. A future firmware release will work around this problem automatically.

PR49812 MANUAL: Better explanation of sweep delay needed.

Models affected:

All 2450

Symptom:

Recent changes to the sweep commands did not get added to the 2450 Reference Manual in time for first release.

Workaround:

The sweep commands accept a delay setting of 0 for no delay, -1 for auto delay (excluding the list command), or constant value between 50 us and 10000 s.

The TSP sweep commands are:

```
smu.source.sweeplinear()  
smu.source.sweeplinearstep()  
smu.source.sweeplist()  
smu.source.sweeplog().
```

The SCPI sweep commands are :

```
:SOURce[1]:SWEep:<function>:LINear  
:SOURce[1]:SWEep:<function>:LINear:STEP  
:SOURce[1]:SWEep:<function>:LIST  
:SOURce[1]:SWEep:<function>:LOG
```

For `smu.source.sweeplist()` and `:SOURce[1]:SWEep:<function>:LIST`, the delay setting configures a constant delay trigger block in the trigger model.

A delay of zero omits the trigger block.

The configuration list delay settings act independently of the delay specified in the command. Therefore, a double delay may result by utilizing both.

The next version of the 2450 Reference Manual will be updated.

PR49835 Recalling measure configuration list causes error 823.

Models affected:

All 2450

Symptom:

When recalling the measure configuration list before the source configuration list, the error code 823 may be displayed.

Workaround:

When recalling both source and measure configuration lists, always recall the source configuration list before the measure. This order ensures that dependencies between source and measure settings will be properly handled.

PR49885 MANUAL: Source delay is incorrect for default settings and resistance measure function.

SCPI: :SOURce[1]:<function>:DElay

TSP: smu.source.delay

Models affected:

All 2450

Symptom:

In the 2450 Reference Manual, the documentation for the command `smu.source.delay` claims the default setting is `.001`. This is NOT TRUE. There is no default value for the command `smu.source.delay` and if queried without being set, will return the last auto delay setting.

The manual also states “If you turn auto delay back on, the programmed source delay value is added to the auto delay time.” This is also incorrect.

Workaround:

Make sure to set an initial value for `smu.source.delay`.

The next version of the 2450 Reference Manual will be corrected.

PR49892 Changes to the Reference Manual.

Models affected:

All 2450

Symptom:

A number of miscellaneous late changes were not added in time to Rev-A revision of the 2450 Reference Manual. Some of the key issues have been documented here.

A) The following commands have been removed from the product:

SCPI: `SYSTem:BEEPer:STATe`

TSP: `beeper.enable`

These commands have been used in various places in the manual and in documented examples. These references will be removed in the next revision of the manual. No substitute commands have been provided.

B) Digital I/O behavior:

- a. For digital I/O lines, changing the line mode to input will set the line state high.
- b. For digital I/O lines, changing the line mode to output will set the line state low.
- c. When configuring digital I/O, the output side of the line should be configured before the input side to avoid a false input trigger detection

C) Using the reset() command:

- a. On page 3-125 in the Reference Manual, the following NOTE is INCORRECT. The command `tsplink.initialize()` DOES change the states of the individual nodes in the system.

NOTE

Using the `reset()` command in a TSP-Link network differs from using the `tsplink.reset()` or `tsplink.initialize()` command. The `tsplink.reset()` or `tsplink.initialize()` command reinitializes the TSP-Link network, but does not change the state of the individual nodes in the system.


D) Resistance Mode Changes: Auto Ohms vs. Manual Ohms:

- a. Significant changes were made to the way resistance mode was documented in Revision A of the 2450 Reference Manual. Below is a summary of differences in the Reference Manual vs. the actual implementation. The Reference Manual will be updated to reflect these changes in Revision B of the 2450 Reference Manual. Sections affected are 2-91, 6-46, 8-116, and 9-14.
- b. The term “Auto Ohms” has been removed from the user interface. The user interface now presents “Ohmmeter” as a One-Touch Quick Setup (see diagram below).
- c. The term “Manual Ohms” has been removed from the user interface. The user interface now presents “Resistance” as a Measure function vs. Voltage or Current Source (see diagram below).
- d. The following commands have been eliminated
 - i. `[SENSe[1]]:RESistance:MODE AUTO | MANual` (SCPI, section 6-46)
 - ii. `smu.measure.resistancemode = smu.RESISTANCE_AUTO` or `smu.RESISTANCE_MANUAL` (TSP, section 8-116)
- e. The following existing commands have a new argument as follows
 - i. `[SENSe[1]]:<function>:UNIT WATT | OHM | VOLT | AMP` (section 6)
 - ii. `smu.measure.unit = <WATT> <OHM> <VOLT> <AMP>`
- f. New TSP Command Usage:
 - i. “Manual Ohms” → Measures resistance by sourcing voltage, measuring current, and calculating the resistance reading.
 - `smu.source.func = smu.FUNC_DC_VOLTAGE`
 - `smu.measure.func = smu.FUNC_DC_CURRENT`
 - `smu.measure.unit = smu.UNIT_OHM`

OR

 - `smu.source.func = smu.FUNC_DC_CURRENT`
 - `smu.voltage.func = smu.FUNC_DC_VOLTAGE`
 - `smu.measure.unit = smu.UNIT_OHM`
 - ii. “Auto Ohms” → Measures resistance by sourcing current, measuring voltage, and calculating the resistance reading. In this case, the source current and source limit are automatically calculated and set.
 - `smu.measure.func = smu.FUNC_RESISTANCE`

- g. New SCPI Command Usage:
 - i. "Manual Ohms" (see definition above)
 - SOURce:FUNC VOLTage
 - [SENSe[1]]:FUNC "CURRent"
 - [SENSe[1]]:CURRent:UNIT OHMOR
 - SOURce:FUNC CURRent
 - [SENSe[1]]:FUNC "VOLTage"
 - [SENSe[1]]:VOLTage:UNIT OHM
 - ii. "Auto Ohms" (see definition above)
 - [SENSe[1]]:FUNC "RESistance"
- h. Front panel user interface setting of Manual vs. Auto Ohms measurements
<see the following figure for details>




SVMI (Ω) SIMV (Ω)

Both exhibit "Manual" Ohms behavior (works just like Power by setting units to Ohms and going to SVMI or SIMV)

Exhibits "Auto" Ohms behavior

SVMR



PR49955 Cannot repeatedly reconnect with LAN triggers.

Models affected:

All 2450

Symptom:

Certain scripts (where LAN connections are quickly and repeatedly disconnected and reconnected in rapid succession) may cause a failed connection.

Workaround:

Due to limited socket resources, the safest rate of making LAN connections is 1 connection per second. If there is need for more than one LAN connection per second, the total number of socket resources available is approximately 180, and after a socket is closed, it will take 2 minutes to become available again.

PR50042 MANUAL: TSP-Link mode command only supports open drain.

Models affected:

All 2450

Symptom:

In the 2450 Reference Manual, the documentation erroneously states that the TSP command `tsplink.line[N].mode` accepts the following parameters:

```
tsplink.MODE_DIGITAL_IN
tsplink.MODE_DIGITAL_OUT
tsplink.MODE_TRIGGER_IN
tsplink.MODE_TRIGGER_OUT
```

Workaround:

Do not use the parameters listed above in the command `tsplink.line[N].`

The next version of the 2450 Reference Manual will be corrected.

PR50188 MANUAL: The source sweep list function does not support `smu.DELAY_AUTO.`

Models affected:

All 2450

Symptom:

In the 2450 Reference Manual, the documentation incorrectly states that the source sweep list function supports the setting `smu.DELAY_AUTO.`

Workaround:

Do not use the setting -1 for delay in the following command:

```
:SOURce[1]:SWEep:<function>:LIST
```


Do not use the setting `smu.DELAY_AUTO` in the following command:

```
smu.source.sweeplist()
```

The next version of the 2450 Reference Manual will be corrected.

PR50228 The `display.screen` command has been changed.

Models affected:

All 2450

Symptom:

The TSP attribute command, `display.screen`, has been replaced with a TSP function, `display.changescreen()`. The parameters to the new function are the same that `display.screen` previously took as a set attribute.

The SCPI query command `DISPlay:SCReen?` does not exist.

The `DISPlay:SCReen` command is only intended to change the screen view NOT to query which view is active

Workaround:

N/A

PR50231 Need to Add Customer Calibration.

Models affected:

All 2450

Symptom:

Because the 2450 added two lower current ranges and one lower voltage range, existing 2400 customer calibration hardware will not work on the 2450. Keithley is working on a recommended customer calibration equipment list, but for now, customer calibration of the 2450 is not supported.

Workaround:

Keithley plans to support customer calibration within six months after shipping the initial Model 2450. Please see <https://www.tek.com/keithley> for updates.

PR50350 Trying to print beyond buffer dimensions causes timeout for new buffer.

Models affected:

All 2450

Symptom:

Attempting to print buffer elements that are outside the range of `[1, bufferVar.n]` may cause a script to hang or a bus command to timeout.

Workaround:

Prior to using `print()` command with a buffer or `printbuffer()`, the elements or bounds provided should be checked to ensure that they are between 1 and `bufferVar.n`, inclusively.

PR50378 Config lists generated by the sweep API don't get saved to the config script.

Models affected:

All 2450

Symptom:

Changes made to source config lists generated using the sweep API are not retained when saving the configuration.

Workaround:

Move all points in the config list generated using the sweep API to a new config list. This can be accomplished by first, creating a new config list. Next, iteratively recall each point from the sweep config list and store it to the new config list. Then delete the config list generated by the sweep API. Finally, build a custom trigger model that uses the new config list.

PR50379 Customer trigger model is overwritten when restoring pre-boxed sweep.

Models affected:

All 2450

Symptom:

Changes made to trigger models generated using the sweep API are not retained when saving the configuration.

Workaround:

Move all points in the config list generated using the sweep API to a new config list. This can be accomplished by first, creating a new config list. Next, iteratively recall each point from the sweep config list and store it to the new config list. Then delete the config list generated by the sweep API. Finally, build a custom trigger model that uses the new config list.

PR50404 TSP-Link does not reset properly on some units.

Models affected:

All 2450

Symptom:

TSP-Link reset or initialization may consistently fail on certain units. The unit being reset or initialized may ignore the reset or initialization command, stop responding to bus commands, and/or display "Slave" in the communications status indicator.

Workaround:

If the reset or initialization command is ignored, try calling it again. It may necessary to repeat this action up to ten times. If the command causes a time-out for bus communications and/or "Slave" is displayed in the communications status indicator for the unit being reset or initialized, then it is necessary to choose a different unit to be the TSP-Link master.

PR50497 SCPI command syntax checking: Error is not generated if parameter is not valid long or short form of the specified command.

Models affected:

All 2450

Symptom:

The 2450 fails to generate an error when the parameter to a SCPI command does not match either the short or long form of the parameter being specified. Instead, the unit will accept any number of characters between the short and long form as being valid. For example, in the following list, only the first two examples should be allowed, however, the additional four examples are being accepted as valid. In a future firmware release, the additional four examples will generate an error message.

COMMAND	v1.0.0 Firmware	Future Firmware
:SYSTem:EVENTlog:COUNT? INF	OK	OK
:SYSTem:EVENTlog:COUNT? INFORMATIONAL	OK	OK
:SYSTem:EVENTlog:COUNT? INFO	OK	SYNTAX ERROR
:SYSTem:EVENTlog:COUNT? INFORM	OK	SYNTAX ERROR
:SYSTem:EVENTlog:COUNT? INFORMAT	OK	SYNTAX ERROR
:SYSTem:EVENTlog:COUNT? INFORMATION	OK	SYNTAX ERROR

Workaround:

Only send a valid short or long form of the SCPI command parameter. Based on the example listed, send either INF or INFORMATIONAL for the related command. This will avoid new syntax errors when upgrading to new 2450 firmware in the future.

PR51449 Calibration Date is set to 03/16/1996 after updating 1.0.0i to 1.1.0s.

Models affected:

All 2450

Symptom:

After upgrading the 2450 firmware from version v1.0.0i to v1.1.0s, the Calibration Date is 03/16/1996. Do NOT be alarmed. This issue has NO IMPACT on calibration and calibration values. The issue is that from v1.0.0i to v1.1.0s, a new date field was added and it has not been initialized properly. Also, the date headings have also changed to differentiate between Adjust Date and Calibration Date (e.g. Verification Date). See the diagrams below.

v1.0.0i firmware

v1.1.0s firmware

SYSTEM INFORMATION	
Serial Number	01419971
Version	1.0.0i
Detected Line Frequency	60 Hz
Calibration Adjust Date	08/14/2014
Calibration Adjust Count	1

SYSTEM INFORMATION	
Serial Number	01419971
Version	1.1.0s
Detected Line Frequency	60 Hz
Adjust Date	08/14/2014
Adjust Count	1
Calibration Date	03/16/1996

Before, there was only one date field named “Calibration Adjust Date.” This was the date that the 2450 was last calibrated WITH adjustment. Starting with the v1.1.0s firmware, a new date named “Calibration Date” was added to display and differentiate between the Adjust Date and Calibration (without adjust) Date. The new “Adjust Date” is the same field as the old “Calibration Adjust Date.” The new “Calibration Date” is brand new field and this will be the date the 2450 was last calibrated WITHOUT adjustment. Since the new “Calibration Date” field did not exist with v1.0.0i firmware, this new date is un-initialized and has defaulted to 03/16/1996. Again, this has zero impact on the original factory calibration and does not impact the factory stored calibration constants in any way.

Workaround:

This date will be properly set the next time the 2450 is returned to Keithley or a designated field service office for recalibration. If you insist on updating the “Calibration Date” to equal the “Adjust Date”, please refer to the “Model 2450 Interactive SourceMeter Calibration Manual,” document number 2450-905-01, available at <https://www.tek.com/keithley>.