
AMD Geode™ LX DB800 Development Board Updated Ethernet Driver Notification



1.0 Scope

The intent of this document is to notify AMD Geode™ LX DB800 development board users that an updated Ethernet driver for the board is available and to describe an issue that the updated driver resolves.

2.0 Discussion

There are instances when the LX DB800 board is running Windows® XP that the Ethernet port appears disconnected, even when the cable is connected.

Alternately, the issue appears as if the LX DB800 board is unable to find the network even with an Ethernet cable connected to a functioning board.

This issue is resolved with an updated version of the Ethernet controller driver and is available from Realtek at:

- <http://w3serv.realtek.com.tw/downloads/downloads1-3.aspx?software=True&refdesign=True&spec=True&other=True&series=2003072&lineID=1&famID=4>

© 2006 Advanced Micro Devices, Inc. All rights reserved.

The contents of this document are provided in connection with Advanced Micro Devices, Inc. ("AMD") products. AMD makes no representations or warranties with respect to the accuracy or completeness of the contents of this publication and reserves the right to make changes to specifications and product descriptions at any time without notice. No license, whether express, implied, arising by estoppel or otherwise, to any intellectual property rights is granted by this publication. Except as set forth in AMD's Standard Terms and Conditions of Sale, AMD assumes no liability whatsoever, and disclaims any express or implied warranty, relating to its products including, but not limited to, the implied warranty of merchantability, fitness for a particular purpose, or infringement of any intellectual property right.

AMD's products are not designed, intended, authorized or warranted for use as components in systems intended for surgical implant into the body, or in other applications intended to support or sustain life, or in any other application in which the failure of AMD's product could create a situation where personal injury, death, or severe property or environmental damage may occur. AMD reserves the right to discontinue or make changes to its products at any time without notice.



www.amd.com

TRADEMARKS

AMD, the AMD Arrow logo, and combinations thereof, and Geode are trademarks of Advanced Micro Devices, Inc.

Windows is a registered trademark of Microsoft Corporation in the United States and/or other jurisdictions.

Other product names used in this publication are for identification purposes only and may be trademarks of their respective companies.