



**IAR Systems** 

website

## Technical Note 30605

# Warning[25]: Label 'xxxxx' is defined pubweak in a section implicitly declared root

EW targets: ARM, STM8

EW component: Assembler Keywords: assembly

Last update: January 12, 2015

#### Problem

After upgrading to... EWARM 7.10.1 EWSTM8 2.10.1 ...the Warning[25] is issued during assembly of a file that assembled without warning on earlier version of the Embedded Workbench.

#### Solution

To avoid the warning, add ":NOROOT" to the "SECTION" control directive. Add the ":NOROOT" to the left of the ()-part of the line.

```
PUBWEAK NMI_Handler
SECTION .text:CODE:REORDER:NOROOT(1)
NMI_Handler
```

#### Background

The assembler is issuing Warning[25] for a deprecated assembler construction.

The deprecated assembler source construction looks like this:

```
PUBWEAK NMI_Handler
SECTION .text:CODE:REORDER(1)
NMI_Handler
```

## Details

The assembler control directive of "SECTION" consists of:

SECTION section :type [:flag] [(align)]

The change is **only** to be made among the **flag** items. I.e. don't change the **"SECTION"**, **"section"**, **":type"** nor the **"[(align)]"** parts of the line. (For example if the *alignment* is expressed as (2) then keep it at (2). (The (2) stands for an alignment of 4 bytes, as the (2) is the power of two to which the address should be aligned.))

The "[:flag]"-part can have these flags: ROOT (the default mode) or NOROOT

and

REORDER or NOREORDER (the default mode)

Where now the Warning from the Assembler shows that the **"explicit noroot"**, due to the directive **"PUBWEAK"**, mismatch the default mode, which gives an **"implied root"** 

So the **"explicit noroot"**, from **"PUBWEAK**", should be matched with the flag **"NOROOT"**.

The details for the assembler control directive of "SECTION" can be found in the chapter "Section control directives" in the "IAR Assembler™ Reference Guide."

All product names are trademarks or registered trademarks of their respective owners.