

## DS3151/DS3152/DS3153/DS3154 Single/Dual/Triple/Quad DS3/E3/STS-1 LIUs

## www.maxim-ic.com

## **REVISION B1 ERRATA**

The errata listed below describe situations where DS3151/DS3152/DS3153/DS3154 revision B1 components perform differently than expected or differently than described in the data sheet. Dallas Semiconductor intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS3151/DS3152/DS3153/DS3154 revision B1 components. Revision B1 components are branded on the topside of the package with a six-digit code in the form yywwB1, where yy and ww are two-digit numbers representing the year and workweek of manufacture, respectively. To obtain an errata sheet on another DS3151/DS3152/DS3153/DS3154 die revision, visit the website at www.maxim-ic.com/errata.

There are no known errata for this revision of the device at this time.

1 of 1 REV: 030807