



Ken Eckert <eckertkp@gmail.com>

Re: [HP-Agilent-Keysight-equipment] LCR Meters????

Dave Wise <david_wise@phoenix.com>
Reply-To: HP-Agilent-Keysight-equipment@groups.io
To: HP-Agilent-Keysight-equipment@groups.io

Sun, Sep 29, 2019 at 1:26 PM

On Sun, Aug 18, 2019 at 07:20 AM, Dave McGuire wrote:

Dave McGuire, I found my old GR 1680-A notes from 2012. Here are the highlights.

I just fixed a new failure. Symptom: Inoperative; display dim. (Amusingly, I discovered it while investigating another instrument that was also a bad PS cap.) Turned out to be a weak rivet joint at C502's terminals. (That's 12mF 25V, a big computer-grade part.) I just wrenched the lugs around until I hit a tight spot. Should last for years; eventually I'll have to wire in a new part - on a terminal strip since I don't feel like paying for one big enough to fit the clamp.

Groups.io Links:

You receive all messages sent to this group.

[View/Reply Online \(#99641\)](#) | [Reply To Group](#) | [Reply To Sender](#) | [Mute This Topic](#) | [New Topic](#)

[Your Subscription](#) | [Contact Group Owner](#) | [Unsubscribe \[eckertkp@gmail.com\]](#)
