### Revision: 1.1 Date: 14.04.2015

# ACCORDING TO EC-REGULATIONS 1907/2006 (REACH), 1272/2008 (CLP) & 453/2010



www.vishaypg.com

1.	SECTION 1: IDENTIFICATION OF THE S	SUBSTANCE/MIXTURE AND OF THE COMPANY/UNDERTAKING
1.1	Product identifier	
	Product Name	M-Line 450-20S Solder
	Chemical Name	Mixture
	CAS No.	Mixture
	EINECS No.	Mixture
	REACH Registration No.	None assigned.
1.2	Recommended use of the chemical and restrict on use	tions
	Identified Use(s)	PC38 Welding and soldering products (with flux coatings or flux cores.), flux
		products
	Uses Advised Against	None known.
1.3	Supplier's details	
	Company Identification	VISHAY MEASUREMENTS GROUP UK LTD
		Stroudley Road
		Basingstoke
		Hampshire
		RG24 8FW
		United Kingdom
	Telephone	+44 (0) 1256 462131
	Fax	+44 (0) 1256 471441
	E-Mail (competent person)	mm.uk@vishaypg.com
1.4	Emergency Phone No.	(00-1) 703-527-3887
		CHEMTREC

### 2. SECTION 2: HAZARDS IDENTIFICATION

2.1	Directive 67/548/EEC & Directive 1999/45/EC	Not classified as dangerous for supply/use.
2.2	Label elements	According to Regulation (EC) No. 1272/2008 (CLP)
	Product Name	M-Line 450-20S Solder
	Hazard Pictogram(s)	None assigned.
	Signal Word(s)	None assigned.
	Hazard Statement(s)	None assigned.
	Precautionary Statement(s)	None assigned.
	Additional Information	None.
2.3	Other hazards	None.

## 3. SECTION 3: COMPOSITION/INFORMATION ON INGREDIENTS

#### 3.2 Mixtures

No classifiable hazardous ingredient(s).

4.

Revision: 1.1 Date: 14.04.2015

# ACCORDING TO EC-REGULATIONS 1907/2006 (REACH), 1272/2008 (CLP) & 453/2010

**SECTION 4: FIRST AID MEASURES** 



www.vishaypg.com

4.1	Description of first aid measures	
	Inhalation	If breathing is difficult, remove victim to fresh air and keep at rest in a position
	Skin Contact	comfortable for breathing.
	Skin Contact	Wash with plenty of water. If irritation (redness, rash, blistering) develops, get medical attention.
	Eye Contact	Rinse cautiously with water for several minutes. Remove contact lenses, if
		present and easy to do. Continue rinsing. If eye irritation persists, get medical
	Ingestion	advice/attention. Wash out mouth with water and give 200-300 ml (half a pint) of water to drink.
		Do not induce vomiting. If symptoms develop, obtain medical attention.
4.2	Most important symptoms and effects, both acute and	None anticipated.
4.3	delayed Indication of any immediate medical attention and	Treat symptomatically. In case of burns immediately cool affected skin as long
4.0	special treatment needed	as possible with cold water.
5.	SECTION 5: FIREFIGHTING MEASURES	
5.1	Extinguishing media	
-	Suitable Extinguishing media	As appropriate for surrounding fire.
	Unsuitable extinguishing media	Do not use water on fires when molten metal is present.
5.2	Special hazards arising from the substance or mixture	Solder containing antimony may liberate antimony oxide if heated above 537°C.
5.3	Advice for fire-fighters	Fire fighters should wear complete protective clothing including self-contained
		breathing apparatus. Do not breathe fumes. Keep containers cool by spraying
		with water if exposed to fire. Avoid run off to waterways and sewers.
6.	SECTION 6: ACCIDENTAL RELEASE MEAS	JRES
6.1	Personal precautions, protective equipment and	Ensure adequate ventilation. Use personal protective equipment as required.
6.1	Personal precautions, protective equipment and emergency procedures	See Section: 8. Melted solder will solidify on cooling and can be scraped up.
6.1		See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing
	emergency procedures	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces.
6.1 6.2		See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or
	emergency procedures	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces.
6.2 6.3	emergency procedures Environmental precautions Methods and material for containment and cleaning up	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible.
6.2	emergency procedures Environmental precautions Methods and material for containment and cleaning	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for
6.2 6.3 6.4	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible.
6.2 6.3 6.4 7.	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13
6.2 6.3 6.4	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing
6.2 6.3 6.4 7.	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation.
6.2 6.3 6.4 7.	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation. Use personal protective equipment as required. See Section: 8. Do not eat,
6.2 6.3 6.4 7.	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation.
6.2 6.3 6.4 7.	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation. Use personal protective equipment as required. See Section: 8. Do not eat, drink or smoke when using this product. Wash hands before breaks and after
6.2 6.3 6.4 7. 7.1	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE Precautions for safe handling Conditions for safe storage, including any incompatibilities	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation. Use personal protective equipment as required. See Section: 8. Do not eat, drink or smoke when using this product. Wash hands before breaks and after work. When molten: Keep from any possible contact with water. Store in a well-ventilated place.
6.2 6.3 6.4 7. 7.1	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE Precautions for safe handling Conditions for safe storage, including any incompatibilities Storage temperature	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation. Use personal protective equipment as required. See Section: 8. Do not eat, drink or smoke when using this product. Wash hands before breaks and after work. When molten: Keep from any possible contact with water. Store in a well-ventilated place. Ambient.
6.2 6.3 6.4 7. 7.1	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE Precautions for safe handling Conditions for safe storage, including any incompatibilities Storage temperature Storage life	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation. Use personal protective equipment as required. See Section: 8. Do not eat, drink or smoke when using this product. Wash hands before breaks and after work. When molten: Keep from any possible contact with water. Store in a well-ventilated place. Ambient. Stable under normal conditions.
6.2 6.3 6.4 7. 7.1	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE Precautions for safe handling Conditions for safe storage, including any incompatibilities Storage temperature	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation. Use personal protective equipment as required. See Section: 8. Do not eat, drink or smoke when using this product. Wash hands before breaks and after work. When molten: Keep from any possible contact with water. Store in a well-ventilated place. Ambient. Stable under normal conditions. Store away from sources of sulfur. Keep away from: Acids, Chlorine and Strong
6.2 6.3 6.4 7. 7.1	emergency procedures Environmental precautions Methods and material for containment and cleaning up Reference to other sections SECTION 7: HANDLING AND STORAGE Precautions for safe handling Conditions for safe storage, including any incompatibilities Storage temperature Storage life	See Section: 8. Melted solder will solidify on cooling and can be scraped up. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Avoid release to the environment. Do not allow to enter drains, sewers or watercourses. Allow product to cool/solidify and pick up as a solid. Transfer to a container for disposal. Recover or recycle if possible. See Section: 8, 13 Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Ensure adequate ventilation. Use personal protective equipment as required. See Section: 8. Do not eat, drink or smoke when using this product. Wash hands before breaks and after work. When molten: Keep from any possible contact with water. Store in a well-ventilated place. Ambient. Stable under normal conditions.

Revision: 1.1 Date: 14.04.2015

### ACCORDING TO EC-REGULATIONS 1907/2006 (REACH), 1272/2008 (CLP) & 453/2010

www.vishaypg.com

products. See Section: 1.2

#### 8. SECTION 8: EXPOSURE CONTROLS/PERSONAL PROTECTION

- 8.1 **Control parameters**
- 8.1.1 **Occupational Exposure Limits**
- 8.1.2 **Biological limit value**
- 8.1.3 **PNECs and DNELs**
- 8.2 **Exposure controls**
- 8.2.1 Appropriate engineering controls
- Individual protection measures, such as personal 8.2.2 protective equipment (PPE)

Not applicable. Not established. Not established.

Ensure adequate ventilation. or Use appropriate containment. Atmospheric levels should be controlled using the principles of good occupational hygiene practice.

General hygiene measures for the handling of chemicals are applicable. Avoid breathing smoke fumes during soldering. Use caution to avoid breathing fumes if a gas torch is used to cut up large pieces. Wash hands before breaks and after work. Do not eat, drink or smoke at the work place.

Eye/ face protection





Hand protection: Wear impervious gloves (EN374).

When molten: Goggles or Full face shield.

Respiratory protection



Thermal hazards 8.2.3 **Environmental Exposure Controls**  In case of inadequate ventilation wear respiratory protection. Open system(s): Wear suitable respiratory protective equipment.

Not applicable. Avoid release to the environment.

#### 9. **SECTION 9: PHYSICAL AND CHEMICAL PROPERTIES**

#### 9.1 Information on basic physical and chemical properties

Appearance	Silver - Grey metal in wire form
Odour	Not available.
Odour threshold	Not available.
рН	Not available.
Melting point/freezing point	Not available.
Initial boiling point and boiling range	Not available.
Flash point	Not applicable.
Evaporation rate	Not applicable.
Flammability (solid, gas)	Non-flammable.
Upper/lower flammability or explosive limits	Not applicable.
Vapour pressure	Not available.
Vapour density	Not available.
Relative density	>1 (H2O = 1)
Solubility(ies)	Insoluble in water.
Partition coefficient: n-octanol/water	Not available.
Auto-ignition temperature	Not available.
Decomposition Temperature	Not available.
Viscosity	Not available.
Explosive properties	Not explosive.
Oxidising properties	Not oxidising.

#### Revision: 1.1 Date: 14.04.2015

# ACCORDING TO EC-REGULATIONS 1907/2006 (REACH), 1272/2008 (CLP) & 453/2010

www.vishaypg.com

MENTS Brond

9.2	Other information	None.
10.	SECTION 10: STABILITY AND REACTIVITY	
10.1	Stability and reactivity	Stable under normal conditions.
10.2	Chemical stability	Stable under normal conditions.
10.3	Possibility of hazardous reactions	Reacts vigorously with chlorine and oxidising agents.
10.4	Conditions to avoid	None known.
10.5	Incompatible materials	Store away from sources of sulfur. Keep away from: Acids, Chlorine and Strong
		oxidising agents.
		When molten: Keep from any possible contact with water.
10.6	Hazardous decomposition product(s)	Solder containing antimony may liberate antimony oxide if heated above 537°C.
11.	SECTION 11: TOXICOLOGICAL INFORMATI	ION
11.1	Information on toxicological effects (Substances in p	preparations / mixtures)
	Acute toxicity	
	Ingestion	Based upon the available data, the classification criteria are not met.
	0	Acute Toxicity Estimate Mixture Calculation: Estimated LC50 > 2000 mg/kg
		bw/day.
	Inhalation	Based upon the available data, the classification criteria are not met.
		Acute Toxicity Estimate Mixture Calculation: Estimated LC50 >20.0 mg/l.
	Skin Contact	Based upon the available data, the classification criteria are not met.
		Acute Toxicity Estimate Mixture Calculation: Estimated LC50 > 2000 mg/kg
		bw/day.
	Skin corrosion/irritation	Based upon the available data, the classification criteria are not met.
	Serious eye damage/irritation	Based upon the available data, the classification criteria are not met.
	Respiratory or skin sensitization	Based upon the available data, the classification criteria are not met.
	Germ cell mutagenicity	Based upon the available data, the classification criteria are not met.
	Carcinogenicity	Based upon the available data, the classification criteria are not met.
	Reproductive toxicity	Based upon the available data, the classification criteria are not met.
	STOT - single exposure	Based upon the available data, the classification criteria are not met.
	STOT - repeated exposure	Based upon the available data, the classification criteria are not met.
	Aspiration hazard	Based upon the available data, the classification criteria are not met.
11.2	Other information	Based upon the available data, the classification criteria are not met.
12.	SECTION 12: ECOLOGICAL INFORMATION	
12.1	Toxicity	Based upon the available data, the classification criteria are not met.

	reality	Babba apon ano avaliablo data, ano biabolindation ontonia aro not mot.
		Estimated Mixture LC50 >100 mg/l (Fish)
12.2	Persistence and degradability	The product is not biodegradable. (metals).
12.3	Bioaccumulative potential	The product has low potential for bioaccumulation. (metal in wire form)
12.4	Mobility in soil	The product is predicted to have low mobility in soil. (metal in wire form)
12.5	Results of PBT and vPvB assessment	Not classified as PBT or vPvB.
12.6	Other adverse effects	None known.

## 13. SECTION 13: DISPOSAL CONSIDERATIONS

#### 13.1 Waste treatment methods

13.2 Additional Information

Solder can be reclaimed. Dispose of contents in accordance with local, state or national legislation.

Disposal of electrical waste must be in accordance with the Waste Electrical and Electronic Equipment Directive (WEEE Directive, 2012/19/EU).

### 14. SECTION 14: TRANSPORT INFORMATION

14.1 UN number

# ADR/RID / IMDG / IATA

Not classified as dangerous for transport.

# Revision: 1.1 Date: 14.04.2015

# ACCORDING TO EC-REGULATIONS 1907/2006 (REACH), 1272/2008 (CLP) & 453/2010

14.2	Proper Shipping Name	Not classified
14.3	Transport hazard class(es)	Not classified
14.4	Packing group	Not classified
14.5	Environmental hazards	Not classified as a Marine Pollutant.
14.6	Special precautions for user	See Section: 2
14.7	Transport in bulk according to Annex II of MARPOL	Not applicable.
	73/78 and the IBC Code	
14.8	Additional Information	None.
15.	SECTION 15: REGULATORY INFORMATION	
15.1	Safety, health and environmental	
	regulations/legislation specific for the substance or	
	mixture	
15.1.1	EU regulations	
	SVHCs	None
15.1.2	National regulations	
	Germany	Water hazard class: Not classified
45.0	•	
15.2	Chemical Safety Assessment	Not available.

## 16. SECTION 16: OTHER INFORMATION

The following sections contain revisions or new statements: 1-16.

References: Existing Safety Data Sheet (SDS), Existing ECHA registration(s) for Tin (CAS# 7440-31-5) and Antimony (CAS# 7440-36-0).

LEGEND	
LTEL	Long Term Exposure Limit
STEL	Short Term Exposure Limit
DNEL	Derived No Effect Level
PNEC	Predicted No Effect Concentration
PBT	PBT: Persistent, Bioaccumulative and Toxic
vPvB	very Persistent and very Bioaccumulative

Training advice: Consideration should be given to the work procedures involved and the potential extent of exposure as they may determine whether a higher level of protection is required.

#### Disclaimers

Information contained in this publication or as otherwise supplied to Users is believed to be accurate and is given in good faith, but it is for the Users to satisfy themselves of the suitability of the product for their own particular purpose. Vishay Precision Group gives no warranty as to the fitness of the product for any particular purpose and any implied warranty or condition (statutory or otherwise) is excluded except to the extent that exclusion is prevented by law. Vishay Precision Group accepts no liability for loss or damage (other than that arising from death or personal injury caused by defective product, if proved), resulting from reliance on this information. Freedom under Patents, Copyright and Designs cannot be assumed.

#### Annex to the extended Safety Data Sheet (eSDS)

No information available.



www.vishaypg.com