



ERRATA SHEET DS21354/DS21Q354

Revision B2 Errata

The errata listed below describe situations where DS21354/DS21Q354 revision B2 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS21354/DS21Q354 revision B2 components. Revision B2 components are branded on the topside of the package with a six-digit code in the form yywwB2, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another DS21354/DS21Q354 die revision, visit our website at www.maxim-ic.com/errata.

There are no known errata for this revision of the device.