

## DS3251/DS3252/DS3253/DS3254 Single/Dual/Triple/Quad DS3/E3/STS-1 LIUs

## www.maxim-ic.com

## **REVISION A3 ERRATA**

The errata listed below describe situations where DS3251/DS3252/DS3253/DS3254 revision A3 components perform differently than expected or differently than described in the data sheet. Dallas Semiconductor intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS3251/DS3252/DS3253/DS3254 revision A3 components. Revision A3 components are branded on the topside of the package with a six-digit code in the form yywwA3, where yy and ww are two-digit numbers representing the year and workweek of manufacture, respectively. To obtain an errata sheet on another DS3251/DS3252/DS3253/DS3254 die revision, visit our website at <a href="https://www.maxim-ic.com/errata">www.maxim-ic.com/errata</a>.

There are no known errata for this revision of the device at this time.

1 of 1 REV: 030807