

Revision A15 Errata

The errata listed below describe situations where DS87C530 revision A15 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS87C530 revision A15 components. Revision A15 components are branded on the topside of the package with a six-digit code in the form yywwA15, where yy and ww are twodigit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another DS87C530 die revision, visit our website at <u>www.maxim-ic.com/errata</u>.

There are no errata on this revision of the device.