


OPTICAL TACHOMETER CALIBRATION ADAPTER





SPECIFICATIONS

General Specifications

Warm Up Time	Double the time since last used up to 20 minutes maximum		
Standard Interface	Transmille Adapter Interface (9 Pin Female 'D' Type connector)		
Temperature Performance	Storage : -5°C to +60°C		
	Operation : 0°C to +50°C		
Relative Humidity	Operation : <80% to 30°C, <70% to 40°C, <40% to 50°C Storage : <95%, non-condensing		
Altitude	Operation : 3000m (10,000ft) Maximum		
	Transit : 12000m (40,000ft) Maximum		
Brightness	1000mcd (wavelength 660nm)		
Duty Cycle	20% (5:1)		
Connections	Voltage	1x BNC connector	
	Current	1x BNC connector	
	Earth Connection	1x Green 4mm Safety Socket	
Indicators	Red LED 8mm 20° Spread Ultra bright LED mounted in the adaptor case		
Dimensions	17cm x 12cm x 3.5cm		
Warranty Period	1 Year (Parts & Labour)		
Recommended Service Interval	1 Year		
Supplied Connections	1x Adapter Connection Lead		

Range	Resolution	1 Year Rel. %
60 to 60,000 RPM	6 RPM	0.0030

Specifications apply at TCal $\pm 5^{\circ}$ C

Outside this range an allowance of 0.18 x 1 Year Spec. per °C should be added.