Rev: 092704



Revision C1 Errata

The errata listed below describe situations where DS21354/DS21Q354 revision C1 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS21354/DS21Q354 revision C1 components. Revision C1 components are branded on the topside of the package with a six-digit code in the form yywwC1, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another DS21354/DS21Q354 die revision, visit our website at www.maxim-ic.com/errata.

There are no known errata for this revision of the device.