

Revision B2 Errata

The errata listed below describe situations where MAXQ1103 revision B2 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata when the opportunity to redesign the product presents itself.

This errata sheet only applies to MAXQ1103 revision B2 components. Revision B2 components are branded on the topside of the package with a six-digit code in the form yywwB2, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively.

This errata sheet requires an NDA. Contact the BU for availability at www.maxim-ic.com/MAXQ1103.